

ITEM		QUANT	UNIT
	This section is to be read in conjunction with Sections 1 (Preliminaries), Section 2 (Preambles) and all		
	Appendices included within this document.		
0.00	Outline Scope of Works		
	The flood reinstatement scope will include the following works across the site:		
-	Targeted drying of areas prior to works commencement.		
-	Replacement of timber flooring and inspection of sub-floor timber joists.		
	Replacement of flood damaged fire doors		
	Replacement of flood damaged plaster and drywall.		
-	Replacement of flood damaged joinery and finishes, including doors, window cills, skirtings, architraves.		
	Replacement of flood damaged cabinetry, including kitchenette units on a like-for-like basis		
-	Replacement of flood damaged external window		
-	Reinstatement of signpost near Mill 2 and installation of timber fencing to replace collapsed wall to the east of		
	Mill 3.		
-	Decoration and application of new floor finishes		
-	Inspection of electrical services and required repairs.		
	Note: This is not an exhaustive list.		
	Note: Appendix B contains annotated proposed drawings. These drawings are indicative only and should be		
	read alongside this pricing document. The Contractor should price according to the below schedule and should		
	account for the works required on site.		
1.00	The Works		
1.001	Works Segregation		
1.002	All works are to take place behind suitable barriers and be segregated from the public, tenants and staff.	Price each	
	Hoarding will not be required. The Contractor is required to coordinate activities with Tenants to ensure that disruption to their operations is minimised. External works should be carried out behind Chapter 8 barriers.	section below	
	The Contractor is responsible for maintaining site security for the duration of the works. Price for each section		
	below which are included in full below and as ditto throughout:		
1.003	Section 1	1	Item
1.005	Mill 1 - Reception area and corridors (Communal)	T	nem
	Mill 1 - Front Desk Kitchenette		
	Mill 1 - WCs (Communal)		
	Mill 1 - Cleaner's Cupboard (Communal)		
	Mill 1 - Unit AG (Tenant: Sylvan Enterprises of Sherwood Forest Ltd)		
	Mill 1 - External		
1.004	Section 2	1	Item
	Mill 1 - Meeting Room/Community Space		
	Mill 1 - Meeting Room/Community Space Kitchenette		
	Mill 1 - Unit BG (Tenant: Bell Bespoke Interiors Ltd)		
	Mill 1 - Units DG, DG2 and CG (Tenant: Bladen Box Ltd)		
1.005	Section 3	1	Item
	Mill 2 - External		
	Mill 3 - Unit 31		
	Mill 3- Unit RB Mill 3 - External		
1 000			
1.006	Section 4 Mill Court - Entrance Lobby	1	Item
	Mill Court - Unit X (Tenant: Star Crossed Beauty)		
	Mill Court- Unit Y (Tenant: J Scientific Glass)		
	Mill Court - Unit W (Tenant: TBC)		
1.007	Asbestos Works		
1.008	There are no asbestos removal works envisaged within the scope of works. Should asbestos removal works be		
	required this will be instructed by a Contract Instruction. Under no circumstances is any of the above work to		
	be carried out by untrained or inexperienced operatives. An R&D survey will be instructed and will be issued to		
	the Contractor prior to commencement.		
1.009	Fire Alarm & Detection Equipment		
1.010	No works or alterations to the fire alarms are envisaged within the scope of works. Should works be required,		
	these will be instructed via a Contract Instruction. The Contractor is to allow 24/7 access for the Pleasley Vale		
	Site Manager/Security to access the fire alarm control panel in the reception vestibule area of Mill 1 during		
	Section 1 of the Works.		
1.011	Note: The Contractor is not to remove or interfere with any fire alarm sensors or installations. If this is unclear		



Bolower District Council prior to the airm being reactivated, to prevent a false airm. Any damage caused to the fire airm and detection equipment shall be repaired at the sole cost of the Contractor. Image: Contractor Contrecon Contractor Contractor Contractor Contractor Contrac	ITEM		QUANT	UNIT
the fire alarm and detection equipment shall be repaired at the sole cost of the Contractor. Image: Contractor Sole Sole Sole Sole Sole Sole Sole Sole	1.012	Note: Any accidental damage to any fire alarm equipment must be notified to the Contract Administration or		
Image: A state in the stat		Bolsover District Council prior to the alarm being reactivated, to prevent a false alarm. Any damage caused to		
10.14 Note: There are no spinkler systems. 10.15 Fore Fighting Equipment 10.16 Fore Fighting Equipment 10.17 Fetting Contractor's Design and install new fire safety and emergency signage (non-illuminated) to setting locations and where removed during the works. To include directional signage, fire action notice section below signage in all units and common areas. All signage should be in accordance with B 5266-1. Price for each settion below. 10.17 Section 1 ditto 1 Ifti 10.18 Section 3 ditto 1 Ifti 10.19 Section 3 ditto 1 Ifti 10.20 Section 4 ditto 1 Ifti 10.21 Previolonal sum (defined): Allow the provisional sum of £500.00 per section to provide and install hand held 4 4 10.23 Section 1.2 carefully remove chipbard, phynoxold. Rote viol areas are free from debris. Inspect all provide photographic schedule of all gists and sub-floor void for the Contract Administrator. Do not price here for repair works. Repair works will be instructed separately. If required. 1 1 1 10.23 Section 1.2 Medfined): Caulified electrical connections below suspended floors in the communal meeting rom & kitchnente areas on the front desk kitchnente. Repair biologist schedule of all gists and sub-floor void for the Contract Administrator. Administrator. Administrator. Allow to carry out repairs to affected cincuits. 1 </td <td></td> <td>the fire alarm and detection equipment shall be repaired at the sole cost of the Contractor.</td> <td></td> <td></td>		the fire alarm and detection equipment shall be repaired at the sole cost of the Contractor.		
1015 Fire Highling Equipment 1 1026 Contractor's Design Portion: Design and Install new fire safety and emergery signage (non-illuminated) to Price each section below segnage in all unts and common areas. All signage should be in accordance with BS 5266-1. Price for each section below: 1 1 Itt 1027 Section 1 ditto 1 1 Itt 1028 Section 2 ditto 1 1 Itt 1029 Section 4 ditto 1 1 Itt 1020 Section 4 ditto 1 1 Itt 1020 Section 4 ditto 1 1 Itt 1020 Section 4 ditto 1 1 1 1 1020 Section 4 ditto 1	1.013	Sprinkler System		
1016 Contractor's Design Portion: Design and install new fire safety and emergency signage (non-illuminated) to section below signage in all units and common areas. All signage should be in accordance with BS 52661. Price for each section below: Price each 1017 Section 1 ditto 1 Itti 1018 Section 2 ditto 1 Itti 1019 Section 3 ditto 1 Itti 1020 Section 4 ditto 1 Itti 1021 Provisional sum (defined): Allow the provisional sum of 500.00 per section to provide and install hand held extinguishes, fire suppression blankets etc. 1 Itti 1023 Section 1 - Carefully remove chipbach, phywod and floor boards in Nill 1 front desk kitchenette (RDS) to lipits of dramage and signs of rot. Replace from boards on completion of inspection. Provide photographic schedule of all jotts and sub-floor void for the Contract Administrator. Do not price here for repair works. Repair works will be instructed separately, if required. 1 Itti 1023 Section 1 - Provisional sum (defined): Qualified electrician to carry out full inspection and report on any circuits. This includes inspection of all electrical connections below suspended floors in the communal meeting room & kitchenette areas and the front desk kitchenette. Report to be provided to Contract Administrator. All works will be instructed, if required, within Section 2. 1 Itt 1024 Section 2 - Provisional sum (defined): Qualified electric	1.014	Note: There are no sprinkler systems.		
existing locations and where removed during the works. To include directional signage, fire action notice section below: section action not not not not not not not not not n	1.015	Fire Fighting Equipment		
signage in all units and common areas. All signage should be in accordance with BS 5266-1. Price for each section below: Image: Common and State S	1.016	Contractor's Design Portion: Design and install new fire safety and emergency signage (non-illuminated) to	Price each	
section below: Image: control of the section 2 ditto Image: control ditto<		existing locations and where removed during the works. To include directional signage, fire action notice	section below	
1.0.17 Section 1 ditto 1 Int 1.0.18 Section 2 ditto 1 Int 1.0.19 Section 3 ditto 1 Int 1.0.20 Section 4 ditto 1 Int 1.0.21 Provisional sum (defined): Allow the provisional sum of £500.00 per section to provide and install hand held 4 50 1.0.22 Prevents survey and intrusive inspection (Section 1 & 2 only) 1 It 10 1.23 Section 1 - Carefully remove chipboard, phywood and floor boards on completion of inspect surgerd suppended timber sub-floor void. Check void areas are free from debris. Inspect all floor ipoits for dramage and signs of rot. Replace floor boards on completion of inspection. Provide photographic schedule of all joits and sub-floor void. Check void areas are free for meeting room any crusts. This includes inspection of all electrical connections below supended floors in the communal meeting room any checkes supperd suppended timber sub-floor void. Check void areas are free from debris. Inspect all floor joits for damage and signs of rot. Replace floor boards on completion of inspection. Provide photographic schedule of all joits and sub-floor void for the Contract Administrator. Do not price here for repair works. Repair works will be instructed, if required, within Section 2. 1 1 1 0.25 Section 2 - Provisional sum (defined): Qualified electrician to carry out till inspection and report on any crusts. Repair works will be instructed, if required, within Section 2. 1 <td></td> <td>signage in all units and common areas. All signage should be in accordance with BS 5266-1. Price for each</td> <td></td> <td></td>		signage in all units and common areas. All signage should be in accordance with BS 5266-1. Price for each		
10.18 Section 2 ditto 1 It 10.19 Section 3 ditto 1 It 10.20 Section 3 ditto 1 It 10.21 Provisional sum (defined): Allow the provisional sum of £500.00 per section to provide and install hand held extinguishers, fire suppression blankets etc. 1 It 10.22 Pre-works survey and intrusive inspection (Section 1 & 2 only) 1 1 It 10.23 Section 1 - Carefully remove chipboard, plywood and floor boards in Mill 1 front desk kitchenette (R05) to 1 1 1 It 10.23 Section 4 ange and signs of rot. Replace floor boards on completion of inspection. Provide photographic schedule of all joits and sub-floor void for the Contract Administrator. Do not price here for repair works. 1 1 It 10.24 Section 2 - Carefully remove chipboard, plywood and floor boards in Mill 1 Unit EG (communal meeting room & kitchenette areas and the front desk kitchenette. Report to be provided to Contract Administrator. 1		section below:		
10:19 Section 3 ditto 1 11 10:20 Section 3 ditto 1 11 10:20 Section 3 ditto 1 11 10:20 Section 3 ditto 1 11 11 Provisional sum (defined): Allow the provisional sum of £500.00 per section to provide and install hand held 4 55 21 Pre-works surveys and intrusive inspection [Section 1 & 2 coly] 5 1 1 10 22 Pre-works surveys and intrusive inspection [Section 1 & 2 coly] 5 1 1 10 10 23 Section 1 - Carefully remove chipboard, plywood and floor boards on completion of inspection. Provide photographic schedule of all joists and sub-floor void. Check void areas are free form debris. Inspect all floor disk disk kitchenettes area to inspect suppected circuits. This includes inspection of all electrical context Administrator. Do not price here for repair works. Repair works will be instructed circuits. 1 10 10 1024 Section 2 - Carefully remove chipboard, plywood and floor boards in Mill 1 Unit EG (communal meeting room & kitchenette area) to inspect all locy risks for damage and signs of rot. Replace floor boards on completion of inspection. Provide photographic schedule of all joists and sub-floor void for the Contract Administrator. Do not price here for repair works. Repair works will be instructed, if required, within Section 2. 1 1	1.017	Section 1 ditto	1	Item
Section 4 ditto 1 Itt 0.021 Provisional sum (defined): Allow the provisional sum of £500.00 per section to provide and install hand held 4 St 0.022 Pre-works surveys and intrusive inspection 1 & 2 only	1.018	Section 2 ditto	1	Item
1.021 Provisional sum (defined): Allow the provisional sum of £500.00 per section to provide and install hand held 4 51 2.027 Pre-works surveys and intrusive inspection (Section 1.8.2 only) 1 1.023 Section 1 - Carefully remove chipboard, phywood and floor boards in Mill 1 front desk kitchenette (R05) to 1 1.023 Section 1 - Carefully remove chipboard, phywood and floor boards on completion of inspection. Provide photographic schedule of all joists and sub-floor void. Check void areas are free from debris. Inspect all floor ipoists for damage and signs of rot. Replace floor boards on completion of inspection and report on any circuits. This includes inspection of all electrical connections below suspended floors in the communal meeting room & kitchenette areas and the front desk kitchenette. Report to be provided to Contract Administrator. Allow to carry out repairs to affected circuits. 1 1t 1.025 Section 2 - Carefully remove chipboard, phywood and floor boards in Mill 1 Unit EG (communal meeting room & kitchenette area) to inspect suspected suspended timber sub-floor void. Check void areas are free from debris. Inspect all floor joists for damage and signs of rot. Replace floor boards on completion of inspection. Provide photographic schedule of all joista and sub-floor void for the Contract Administrator. Do not price here for repair works. Repair works. Will be instructed, if required, within Section 2. 1 1t 1.026 Section 2 - Provisional sum (defined): Qualified electricia no carry ou trapin's on any ection below defective or damaged finishes and before carrying out any reinstatement works. The Contract Ad	1.019	Section 3 ditto	1	Item
extinguishers, fire suppression blankets etc. 1 0.22 Prew works surveys and intrusive inspection [Section 1 & 2 only] 1 0.23 Section 1 - Carefully remove chipboard, phywood and floor boards in Mill 1 front desk kitchenette (R05) to 1 1 11 Ittis spect suspected suspended timber sub-floor void. Check void areas are free from debris. Inspect all floor 1 124 Section 1 - Provisional sum (defined): Qualified electrical to carry out full inspection and report on any circuits. This includes inspection of all electrical connections below suspended floors in the communal meeting room & kitchenette areas and the front desk kitchenette. Report to be provided to Contract Administrator. Allow to carry out repairs to affected circuits. 1 5L 12025 Section 2 - Carefully remove chipboard, phywood and floor boards in Mill 1 Unit EG (communal meeting room & kitchenette areas) to inspect suspected suspended timber sub-floor void. Check void areas are free from debris. Inspect all floor joists for damage and signs of rot. Replace floor boards on completion of inspection. Provide photographic schedule of all joists and sub-floor void for the Contract Administrator. Do not price here for repair works. Repair works will be instructed, if required, within Section 2. 1 1 5L 12026 Section 2 - Provisional sum (defined): Qualified electrical no carry out repairs to affected circuits. 1 5L 12027 Driving and Cleaning works. 1 1 5L 12028	1.020	Section 4 ditto	1	Item
1.022 Pre-works surveys and intrusive inspection (Section 1 & 2 only) 1 1.023 Section 1 - Carefully remove chipboard, phywood and floor boards in Mill 1 front desk kitchenette (RO5) to 1 1 1.024 Section 1 - Carefully remove chipboard, phywood and floor boards on completion of inspection. Provide photographic schedule of all joits and sub-floor void. Check void areas are free from debris. Inspect all floor and sub-floor void for the Contract Administrator. Do not price here for repair works. Repair works will be instructed separately, if required. 1 1 1.024 Section 1 - Provisional sum (defined): Qualified electrician to carry out full inspection and report on any from x kitchenette areas and the front desk kitchenette. Report to be provided to Contract Administrator. Allow to carry out repairs to affected circuits. 1 1 1 1.025 Section 2 - Carefully remove chipboard, phywood and floor boards in Mill 1 Unit EG (communal meeting from x kitchenette areas and the front desk kitchenette. Report to be provided to Contract Administrator. 1 1 1 1.026 Section 2 - Provisional sum (defined): Qualified electrician to carry out full inspection and report on any for repair works. Repair works will be instructed, if required, within Section 2. 1 1 1 0.026 Section 2 - Provisional sum (defined): Qualified electrician to carry out full inspection and report on any for carry out repairs to affected cincuits. 1 1 <t< td=""><td>1.021</td><td>Provisional sum (defined): Allow the provisional sum of £500.00 per section to provide and install hand held</td><td>4</td><td>SUM</td></t<>	1.021	Provisional sum (defined): Allow the provisional sum of £500.00 per section to provide and install hand held	4	SUM
1.023 Section 1 - Carefully remove chipboard, plywood and floor boards in Mill 1 front desk kitchenette (R05) to inspect. Provide photographic schedule of all joists and sub-floor void for the Contract Administrator. Do not price here for repair works. Repair works will be instructed separately, if required. It is includes inspection of all electrical connections below suspended floors in the communal meeting room & kitchenette areas and the front desk kitchenette. Report to be provided to Contract Administrator. Allow to carry out repairs to affected circuits. It is the section 1 - Provisional sum (defined): Qualified electrician to carry out full inspection and report on any circuits. This includes inspection of all electrical connections below suspended floors in the communal meeting room & kitchenette areas and the front desk kitchenete. Report to be provided to Contract Administrator. Allow to carry out repairs to affected circuits. It is kitchenette areas and the front desk kitchenete. Report to be provided to Contract Administrator. Do not price here for repair works. Repair works will be instructed, if required, within Section 2. It is kitchenette areas and the front desk kitchenette. Report to boards on completion of inspection. Provide photographic schedule of all joists and sub-floor void for the Contract Administrator. Do not price here for repair works. Repair works will be instructed, if required, within Section 2. It is includes inspection of all electrical connections below suspended floors in the communal meeting room & kitchenette areas and the front desk kitchenette. Report to be provided to Contract Administrator. Allow to carry out repairs to affected circuits. It is a section 2. 10265 Section 1 - Provisional sum (defined): Qualified electrician to carry out full inspection and repord on systemet areas and th		extinguishers, fire suppression blankets etc.		
inspect suspected suspended timber sub-floor void. Check void areas are free from debris. Inspect I all floor Inspect suspected suspended timber sub-floor void for the Contract Administrator. Do not price here for repair works. Repair works will be instructed separately, if required. 1 St circuits. This includes inspection of all electrical connections below suspended floors in the communal meeting room & kitchenette areas and the front desk kitchenette. Report to be provided to Contract Administrator. Allow to carry out repairs to affected circuits. 1 Its Section 2 - Carefully remove chipboard, phywood and floor boards in Mill 1 Unit EG (communal meeting room debris. Inspect all floor joists for damage and signs of rot. Replace floor boards on completion of inspection. Provide photographic schedule of all joists and sub-floor void for the Contract Administrator. Do not price here from debris. Inspect all floor joists for damage and signs of rot. Replace floor boards on completion of inspection. Provide photographic schedule of all joists and sub-floor void for the Contract Administrator. Do not price here from debris. Inspect all mory reinstances and the front desk kitchenete. Report to be provided to Contract Administrator. Allow to carry out repairs to affected circuits. 1 0.026 Section 2 - Provisional sum (defined): Qualified electrician to carry out full inspection and report on any carry and reading works. Repair works, the Contract doministrator. Allow to carry out repairs to affected circuits. Price each section below suspended floors in the communal meeting room and carry out repairs to affected circuits. 0.027 Drying and cleaning works. Contract Administrat	1.022	Pre-works surveys and intrusive inspection (Section 1 & 2 only)		
joists for damage and signs of rot. Replace floor boards on completion of inspection. Provide photographic Schedule of all joists and sub-floor void for the Contract Administrator. Do not price here for repair works. Repair works will be instructed separately, if required. 1 1.024 Section 1 - Provisional sum (defined): Qualified electrician to carry out full inspection and report on any room & kitchnente areas and the front desk kitchnente. Report to be provided to Contract Administrator. 1 2.025 Section 2 - Carefully remove chipboard, plywood and floor boards in Mill 1 Unit EG (communal meeting room & kitchnente areas and the front desk kitchnente. Report to be provided to Contract Administrator. 1 It 2.025 Section 2 - Provisional sum (defined): Qualified electrician to carry out full inspection and report on any repairs to affected circuits. 1 It 2.026 Section 2 - Provisional sum (defined): Qualified electrician to carry out full inspection and report on any circuits. This includes inspection of electrical connections below suspended floors in the communal meeting room & kitchnente areas and the front desk kitchnente. Report to be provided to Contract Administrator. 1 St 2.026 Section 2 - Provisional sum (defined): Qualified electrician to sarry out full inspection and report on any circuits. 1 St 2.027 Drying and cleaning works Price each satter de routiss. Price each section below for the daily testing and recording of moisture in structural materials, using elect	1.023	Section 1 - Carefully remove chipboard, plywood and floor boards in Mill 1 front desk kitchenette (R05) to	1	Item
schedule of all joists and sub-floor void for the Contract Administrator. Do not price here for repair works. Image: Schedule of all joists and sub-floor void for the Contract Administrator. .024 Section 1 - Provisional sum (defined): Qualified electrical connections below suspended floors in the communal meeting room & kitchenette areas and the front desk kitchenette. Report to be provided to Contract Administrator. 1 St .025 Section 2 - Carefully remove chipboard, plywood and floor boards in Mill 1 Unit EG (communal meeting room & kitchenette area) to inspect suspected suspended timber sub-floor void. Check void areas are free from debris. Inspect all floor joists for damage and signs of rot. Replace floor boards on completion of inspection. Provide photographic schedule of all joists and sub-floor void for the Contract Administrator. Do not price here for repair works. Repair works will be instructed, if required, within Section 2. 1 St .026 Section 2 - Provisional sum (defined): Qualified electrician to carry out full inspection and report on any circuits. This includes inspection of all electrical connections below suspended floors in the communal meeting room & kitchenette areas and the front desk kitchenette. Report to be provided to Contract Administrator. Allow to carry out repairs to affected circuits. 1 St .027 Drying and cleaning works Price each Appendix C2. The drying goals are to be agreed with the Contract Administrator following removal of any section below defective or damaged finishes and before carrying out any reinstatement works. The Contractor is to allow for the daily testing and recording of moisture in structural materials, using electrical resi		inspect suspected suspended timber sub-floor void. Check void areas are free from debris. Inspect all floor		
Repair works will be instructed separately, if required. Image: Construction of the construction of the communal meeting room any circuits. This includes inspection of all electrical constructions below suspended floors in the communal meeting room & kitchenette areas and the front desk kitchenette. Report to be provided to Contract Administrator. Allow to carry out repairs to affected dircuits. Image: Construction of the communal meeting room & kitchenette areas in the front desk kitchenette. Report to be provided to Contract Administrator. Allow to carry out repairs to affected dircuits. Image: Construction of the communal meeting room & kitchenette area) to inspect suspended timber sub-floor void. Check void areas are free from debris. Inspect all floor joists for damage and signs of rot. Replace floor boards on completion of inspection. Provide photographic stochedule of all picts and sub-floor void of the Contract Administrator. Do not price here for repair works. Repair works will be instructed, if required, within Section 2. Image: Construction of all electrical connections below suspended floors in the communal meeting room & kitchenette areas and the front desk kitchenette. Report to be provided to Contract Administrator. Allow to carry out repairs to affected circuits. Image: Construction of all electrical connections below suspended floors in the communal meeting room & kitchenette areas and the front desk kitchenette. Report to be provided to Contract Administrator. Allow to carry out repairs to affected circuits. Image: Construction of all electrical context administrator following removal of any section below suspended floors in the contract of any genesities and before carrying out any reinstatement works. The Contractor is to allow for the daily testing and recording of moisture in structural materials, using electrical resistance or calcium carbide methods. All foor testing m				
0.24 Section 1 - Provisional sum (defined): Qualified electricia to carry out full inspection and report on any circuits. This includes inspection of all electrical connections below suspended floors in the communal meeting room & kitchenette areas and the front desk kitchenette. Report to be provided to Contract Administrator. 1 0.25 Section 2 - Carefully remove chipboard, plywood and floor boards in Mill 1 Unit EG (communal meeting room & kitchenette area) to inspect suspected suspended timber sub-floor void. Check void areas are free from debris. Inspect all floor joists for damage and signs of rot. Replace floor boards on completion of inspection. Provide photographic schedule of all joists and sub-floor void for the Contract Administrator. Do not price here for repair works. Repair works will be instructed, if required, within Section 2. 1 It 0.206 Section 2 - Provisional sum (defined): Qualified electrician to carry out full inspection and report on any circuits. This includes inspection of all electricial connections below suspended floors in the communal meeting room & kitchenette areas and the front desk kitchenette. Report to be provided to Contract Administrator. Allow to carry out repairs to affected circuits. 1 St. 0.207 Drying and cleaning works Price each Appendix C2. The drying goals are to be agreed with the Contract Administrator folowing removal of any defective or damage dinisters and before carrying out any reinstatement works. The Contractor is to allow for the daily testing and recording of moisture in structural materials, using electrical resistance or calcuing arbitrator below we defective or damage dinistrator. Price for each section below: 1 It <t< td=""><td></td><td></td><td></td><td></td></t<>				
circuits. This includes inspection of all electrical connections below suspended floors in the communal meeting room & kitchenette areas and the front desk kitchenette. Report to be provided to Contract Administrator. Allow to carry out repairs to affected circuits. 1 0.025 Section 2 - Carefully remove chipboard, plywood and floor boards in Mill 1 Unit EG (communal meeting room & kitchenette area) to inspect suspected suspended timber sub-floor void. Check void areas are free from debris. Inspect all floor joists for damage and signs of rot. Replace floor boards on completion of inspection. Provide photographic schedule of all joists and sub-floor void for the Contract Administrator. Do not price here for repair works. Repair works will be instructed, if required, within Section 2. 1 1 St 0.026 Section 2 - Provisional sum (defined): Qualified electrician to carry out full inspection and report on any circuits. This includes inspection of all electrical connections below suspended floors in the communal meeting room & kitchenette areas and the front desk kitchenette. Report to be provided to Contract Administrator. Allow to carry out repairs to affected circuits. 1 St 0.027 Drying and cleaning works 0.028 Prior to carrying out any reinstatement works, the Contract or is to establish drying goals in accordance with Appendix C2. The drying goals are to be agreed with the Contract Administrator following removal of any section below defective or damaged finishes and before carrying out any reinstatement works. The Contract or sollow for the daily testing and recording of moisture in structural materials, using electrical resistance or calcium carbide method		Repair works will be instructed separately, if required.		
room & kitchenette areas and the front desk kitchenette. Report to be provided to Contract Administrator Allow to carry out repairs to affected circuits.It1.025Section 2 - Carefully remove chipboard, plywood and floor boards in Mill 1 Unit EG (communal meeting room & kitchenette area) to inspect suspected suspended timber sub-floor void. Check void areas are free from debris. Inspect all floor joists for damage and signs of rot. Replace floor boards on completion of inspection. 	1.024	Section 1 - Provisional sum (defined): Qualified electrician to carry out full inspection and report on any	1	SUM
Allow to carry out repairs to affected circuits.Item1.025Section 2 - Carefully remove chipboard, plywood and floor boards in Mill 1 Unit EG (communal meeting room debris. Inspect all floor joists for damage and signs of rot. Replace floor boards on completion of inspection. Provide photographic schedule of all joists and sub-floor void for the Contract Administrator. Do not price here for repair works. Repair works will be instructed, if required, within Section 2.1Ite1.026Section 2 - Provisional sum (defined): Qualified electrician to carry out full inspection and report on any circuits. This includes inspection of all electrical connections below suspended floors in the communal meeting room & kitchenette areas and the front desk kitchenette. Report to be provided to Contract Administrator. Allow to carry out repairs to affected circuits.Price each section 1 and the contract or is to establish drying goals in accordance with Appendix C2. The drying goals are to be agreed with the Contract Administrator following removal of any defective or damaged finishes and before carrying out any reinstatement works. The Contractor is to allow for the daily testing and recording of moisture in structural materials, using electrical resistance or calcium carbide methods. All floor testing must be completed using the hygrometer test as per BS 8204-1. All testing results to be shared with the Contract Administrator. Price for each section below:Price each section 3 ditto.0203Section 2 ditto1Itt.0313Section 3 ditto1Itt.0324Section 3 ditto1Itt.0335Section 1 ditto1Itt.034Section 1 ditto1Itt.034Section 1 ditto <td< td=""><td></td><td>circuits. This includes inspection of all electrical connections below suspended floors in the communal meeting</td><td></td><td></td></td<>		circuits. This includes inspection of all electrical connections below suspended floors in the communal meeting		
0.025 Section 2 - Carefully remove chipboard, plywood and floor boards in Mill 1 Unit EG (communal meeting room & kitchenette area) to inspect suspected suspended timber sub-floor void. Check void areas are free from debris. Inspect all floor joits for damage and signs of rot. Replace floor boards on completion of inspection. Provide photographic schedule of all joits and sub-floor void for the Contract Administrator. Do not price here for repair works. Repair works will be instructed, if required, within Section 2. 1 It is the photographic schedule of all joits and sub-floor void for the Contract Administrator. Do not price here for repair works. Repair works will be instructed, if required, within Section 2. 1 5 0.026 Section 2 - Provisional sum (defined): Qualified electrician to carry out full inspection and report on any circuits. This includes inspection of all electrical connections below suspended floors in the communal meeting room & kitchenette areas and the front desk kitchenette. Report to be provided to Contract Administrator. Allow to carry out repairs to affected circuits. Price carrying out any reinstatement works, the Contractor is to establish drying goals in accordance with Price each Appendix C2. The drying goals are to be agreed with the Contract Administrator following removal of any section below weeks. All floor testing must be completed using the hygrometer test as per BS 8204-1. All testing results to be shared with the Contract Administrator. Price for each section below: 1 It is the carge of the carge of the contract administrator following results to be shared with the Contract Administrator. Price for each section below: 1 It is the carge of the card the carge of the card the carge of the car				
& kitchenette area) to inspect suspected suspended timber sub-floor void. Check void areas are free from debris. Inspect all floor joists for damage and signs of rot. Replace floor boards on completion of inspection. Provide photographic schedule of all joists and sub-floor void for the Contract Administrator. Do not price here for repair works. Repair works will be instructed, if required, within Section 2. 1 0.206 Section 2 - Provisional sum (defined): Qualified electrician to carry out full inspection and report on any circuits. This includes inspection of all electrical connections below suspended floors in the communal meeting room & kitchenette areas and the front desk kitchenette. Report to be provided to Contract Administrator. Allow to carry out repairs to affected circuits. 1 St 0.207 Drying and cleaning works Price each Price each Price each Allow to carry out repairs to affected circuits. Price each Price each Price each Appendix C2. The drying goals are to be agreed with the Contract Administrator following removal of any section below for the daily testing and recording of moisture in structural materials, using electrical resistance or calcium carbide methods. All floor testing must be completed using the hygrometer test as per BS 8204-1. All testing results to be shared with the Contract Administrator. Price for each section below: 1 Itt 0.203 Section 1 ditto 1 Itt 1 Itt 0.303 Section 2 ditto 1 1		Allow to carry out repairs to affected circuits.		
debris. Inspect all floor joists for damage and signs of rot. Replace floor boards on completion of inspection. Provide photographic schedule of all joists and sub-floor void for the Contract Administrator. Do not price here for repair works. Repair works will be instructed, if required, within Section 2.11.026Section 2 - Provisional sum (defined): Qualified electrician to carry out full inspection and report on any circuits. This includes inspection of all electrical connections below suspended floors in the communal meeting room & kitchenette areas and the front desk kitchenette. Report to be provided to Contract Administrator. Allow to carry out repairs to affected circuits.1St1.027Drying and cleaning works we carry out repairs to affected circuits.Price each section 2.Price each section 1 dity and report to be agreed with the Contract Administrator following removal of any section below for the daily testing and recording of moisture in structural materials, using electrical resistance or calcium carbide methods. All floor testing must be completed using the hygrometer test as per BS 8204-1. All testing results to be shared with the Contract Administrator. Price for each section below:1It0.029Section 1 ditto1ItIt0.031Section 2 ditto1It0.032Section 1 ditto1It0.033Section 1 ditto1It0.034Section 1 ditto1It0.035Section 1 ditto1It0.036Section 1 ditto1It0.037Section 1 ditto1It0.038Section 1 ditto1It0.031 <td< td=""><td>1.025</td><td>Section 2 - Carefully remove chipboard, plywood and floor boards in Mill 1 Unit EG (communal meeting room</td><td>1</td><td>Item</td></td<>	1.025	Section 2 - Carefully remove chipboard, plywood and floor boards in Mill 1 Unit EG (communal meeting room	1	Item
Provide photographic schedule of all joists and sub-floor void for the Contract Administrator. Do not price here for repair works. Repair works will be instructed, if required, within Section 2.Image: Contract Administrator. Do not price here for repair works. Repair works will be instructed, if required, within Section 2.0.206Section 2 - Provisional sum (defined): Qualified electrician to carry out full inspection and report on any circuits. This includes inspection of all electrical connections below suspended floors in the communal meeting room & kitchenette areas and the front desk kitchenette. Report to be provided to Contract Administrator. Allow to carry out repairs to affected circuits.Image: Contract Administrator.0.207Drying and cleaning worksPrice each section any certaing works.Price each section below for the daily testing and recording of moisture in structural materials, using electrical resistance or calcium carbide methods. All floor testing must be completed using the hygrometer test as per BS 8204-1. All testing results to be shared with the Contract Administrator. Price for each section below:Image: Contractor is to allow for the daily testing and recording of open drying. The Contractor is to allow for a minimum of 5 days of trageted or general mechanical drying to all retained ground-floor level floors and walls to achieve the agreed drying goals. The progress towards the drying goal is to be monitored and shared with the Contract Administrator. New finishes are only to be installed when the drying goal has been achieved or by agreement with the Contract Administrator. Price for each section below:Image: Contract administrator. Price for each section below:0.029Section 1 dittoImage: Contractor is to allow for a minimum of 5 days of price each targeted or general mec		& kitchenette area) to inspect suspected suspended timber sub-floor void. Check void areas are free from		
for repair works. Repair works will be instructed, if required, within Section 2.Image: Construct a section 2 in the construction of all electrical connections below suspended floors in the communal meeting room & kitchenette areas and the front desk kitchenette. Report to be provided to Contract Administrator. Allow to carry out repairs to affected circuits.Image: Construct administrator. Allow to carry out repairs to affected circuits.Image: Construct administrator. Allow to carry out repairs to affected circuits.Image: Construct administrator. Allow to carry out repairs to affected circuits.Image: Construct administrator following removal of any section below addition of the daily testing and recording of moisture in structural materials, using electrical resistance or calcium carbide methods. All floor testing must be completed using the hygrometer test as per BS 8204-1. All testing results to be shared with the Contract Administrator. Price for each section below:Image: Construct administrator. Price for each section below:0.029Section 1 ditto1Ittelt0.031Section 2 ditto1Ittelt0.033Section 1 ditto1Ittelt0.034Section 1 ditto1Ittelt0.035Section 1 ditto1Ittelt0.036Section 1 ditto1Ittelt0.037Section 1 ditto1Ittelt0.038Section 1 ditto1Ittelt0.034Section 1 ditto1Ittelt0.035Section 1 ditto1Ittelt0.036Section 1 ditto1Ittelt0.037Section 1 ditto1Ittelt0.038Section 1 ditto1It		debris. Inspect all floor joists for damage and signs of rot. Replace floor boards on completion of inspection.		
1.026 Section 2 - Provisional sum (defined): Qualified electrician to carry out full inspection and report on any circuits. This includes inspection of all electrical connections below suspended floors in the communal meeting room & kitchenette areas and the front desk kitchenette. Report to be provided to Contract Administrator. Allow to carry out repairs to affected circuits. 1 St. 0.027 Drying and cleaning works 0.028 Prior to carrying out any reinstatement works, the Contractor is to establish drying goals in accordance with Appendix C2. The drying goals are to be agreed with the Contract Administrator following removal of any defective or damaged finishes and before carrying out any reinstatement works. The Contractor is to allow for the daily testing and recording of moisture in structural materials, using electrical resistance or calcium carbide methods. All floor testing must be completed using the hygrometer test as per BS 8204-1. All testing results to be shared with the Contract Administrator. Price for each section below: 1 Itt 0.028 Section 1 ditto 1 Itt 1 Itt 0.030 Section 1 ditto 1 Itt 1 Itt 0.031 Section 3 ditto 1 Itt 1 Itt 0.033 The building has undergone a period of open drying. The Contractor is to allow for a minimum of 5 days of targeted or general mechanical drying to all retained ground-floor level floors and walls to achieve the agreed drying goals. The progress towards t				
circuits. This includes inspection of all electrical connections below suspended floors in the communal meeting room & kitchenette areas and the front desk kitchenette. Report to be provided to Contract Administrator. Allow to carry out repairs to affected circuits.Image: Contract Administrator1007Drving and cleaning worksPrior to carrying out any reinstatement works, the Contractor is to establish drying goals in accordance with Appendix C2. The drying goals are to be agreed with the Contract Administrator following removal of any defective or damaged finishes and before carrying out any reinstatement works. The Contractor is to allow for the daily testing and recording of moisture in structural materials, using electrical resistance or calcium carbide methods. All floor testing must be completed using the hygrometer test as per BS 8204-1. All testing results to be shared with the Contract Administrator. Price for each section below:1It1.029Section 1 ditto1It1.031Section 3 ditto1It1.032Section 4 ditto1It1.033The building has undergone a period of open drying. The Contractor is to allow for a minimum of 5 days of targeted or general mechanical drying goal is to be monitored and shared with the Contract Administrator. New finishes are only to be installed when the drying goal has been achieved or by agreementPrice each section below1.034Section 1 ditto1It1.035Section 2 ditto1It1.036Section 3 ditto1It1.036Section 3 ditto1It1.037Section 1 ditto1It1.038Section 1 ditto1<		for repair works. Repair works will be instructed, if required, within Section 2.		
circuits. This includes inspection of all electrical connections below suspended floors in the communal meeting room & kitchenette areas and the front desk kitchenette. Report to be provided to Contract Administrator. Allow to carry out repairs to affected circuits.Image: Contract Administrator1007Drving and cleaning worksPrior to carrying out any reinstatement works, the Contractor is to establish drying goals in accordance with Appendix C2. The drying goals are to be agreed with the Contract Administrator following removal of any defective or damaged finishes and before carrying out any reinstatement works. The Contractor is to allow for the daily testing and recording of moisture in structural materials, using electrical resistance or calcium carbide methods. All floor testing must be completed using the hygrometer test as per BS 8204-1. All testing results to be shared with the Contract Administrator. Price for each section below:1It1.029Section 1 ditto1It1.031Section 3 ditto1It1.032Section 4 ditto1It1.033The building has undergone a period of open drying. The Contractor is to allow for a minimum of 5 days of targeted or general mechanical drying goal is to be monitored and shared with the Contract Administrator. New finishes are only to be installed when the drying goal has been achieved or by agreementPrice each section below1.034Section 1 ditto1It1.035Section 2 ditto1It1.036Section 3 ditto1It1.036Section 3 ditto1It1.037Section 1 ditto1It1.038Section 1 ditto1<	1 026	Section 2 - Provisional sum (defined): Qualified electrician to carry out full inspection and report on any	1	SUM
room & kitchenette areas and the front desk kitchenette. Report to be provided to Contract Administrator. Allow to carry out repairs to affected circuits.Image: Contract Administrator.1.027Drving and cleaning worksPrice each section below for the daily testing and recording of moisture in structural materials, using electrical resistance or calcium carbide methods. All floor testing must be completed using the hygrometer test as per BS 8204-1. All testing results to be shared with the Contract Administrator. Price for each section below:1Itel1.029Section 1 ditto1Itel1.031Section 3 ditto1Itel1.033The building has undergone a period of open drying, The Contractor is to allow for a minimum of 5 days of drying goals. The progress towards the drying goal is to be monitored and shared with the Contract Administrator. New finishes are only to be installed when the drying goal has been achieved or by agreement with the Contract Administrator. Price for each section below:Price each section 11.033Section 1 ditto1Ite1.034Section 1 ditto1Ite1.035Section 1 ditto1Ite1.036Section 1 ditto1Ite1.037Section 1 ditto1Ite1.038The building has undergone a period of open drying coll is to be monitored and shared with the Contract Administrator. New finishes are only to be installed when the drying goal has been achieved or by agreement with the Contract Administrator. Price for each section below:1Ite1.033Section 1 ditto1Ite1Ite1.034Section	1.020		1	30101
Allow to carry out repairs to affected circuits.Image: Contract of Contract o				
Drying and cleaning worksImage: cleaning works1.028Prior to carrying out any reinstatement works, the Contractor is to establish drying goals in accordance with Appendix C2. The drying goals are to be agreed with the Contract Administrator following removal of any defective or damaged finishes and before carrying out any reinstatement works. The Contractor is to allow for the daily testing and recording of moisture in structural materials, using electrical resistance or calcium carbide methods. All floor testing must be completed using the hygrometer test as per BS 8204-1. All testing results to be shared with the Contract Administrator. Price for each section below:1Itt Itt.029Section 1 ditto1Itt.030Section 2 ditto1Itt.031Section 4 ditto1Itt.033The building has undergone a period of open drying. The Contractor is to allow for a minimum of 5 days of trig goals. The progress towards the drying goal is to be monitored and shared with the Contract Administrator. New finishes are only to be installed when the drying goal has been achieved or by agreement with the Contract Administrator. Price for each section below:1Itt.033Section 1 ditto1IttItt.034Section 1 ditto1Itt.035Section 1 ditto1Itt.036Section 2 ditto1Itt.037Section 1 ditto1Itt.038Section 1 ditto1Itt.039Section 1 ditto1Itt.031Section 2 ditto1Itt.032Section 1 ditto1Itt <td></td> <td></td> <td></td> <td></td>				
I.028Prior to carrying out any reinstatement works, the Contractor is to establish drying goals in accordance with Appendix C2. The drying goals are to be agreed with the Contract Administrator following removal of any defective or damaged finishes and before carrying out any reinstatement works. The Contractor is to allow for the daily testing and recording of moisture in structural materials, using electrical resistance or calcium carbide methods. All floor testing must be completed using the hygrometer test as per BS 8204-1. All testing results to be shared with the Contract Administrator. Price for each section below:Price each section 1 ditto1.029Section 1 ditto1Itte1.030Section 2 ditto1Itte1.031Section 3 ditto1Itte1.032Section 4 ditto1Itte1.033The building has undergone a period of open drying. The Contractor is to allow for a minimum of 5 days of trying goals. The progress towards the drying goal is to be monitored and shared with the Contract Administrator. Price for each section below:Price each testion below1.034Section 1 ditto1Itte1.035Section 2 ditto1Itte1.036Section 1 ditto1Itte1.037Section 1 ditto1Itte1.038Section 1 ditto1Itte1.039Section 1 ditto1Itte1.031Itte contract Administrator. Price for each section below:Section below1.032Section 1 ditto1Itte1.033The building has undergone a period of open drying goal is to be monitored and shared with th	1.027	Drving and cleaning works		
Appendix C2. The drying goals are to be agreed with the Contract Administrator following removal of any defective or damaged finishes and before carrying out any reinstatement works. The Contractor is to allow for the daily testing and recording of moisture in structural materials, using electrical resistance or calcium carbide methods. All floor testing must be completed using the hygrometer test as per BS 8204-1. All testing results to be shared with the Contract Administrator. Price for each section below:1Itte1.029Section 1 ditto1Itte1.030Section 2 ditto1Itte1.031Section 3 ditto1Itte1.032Section 4 ditto1Itte1.033The building has undergone a period of open drying. The Contractor is to allow for a minimum of 5 days of targeted or general mechanical drying to all retained ground-floor level floors and walls to achieve the agreed drying goals. The progress towards the drying goal is to be monitored and shared with the Contract Administrator. Price for each section below:1Itte1.034Section 1 ditto1Itte1.035Section 1 ditto1Itte1.036Section 2 ditto1Itte1.037Section 1 ditto1Itte1.038Section 1 ditto1Itte1.039Section 1 ditto1Itte1.031Section 1 ditto1Itte1.032Section 1 ditto1Itte1.033Section 1 ditto1Itte1.034Section 1 ditto1Itte1.035Section 2 ditto1Itt	1.028		Price each	
defective or damaged finishes and before carrying out any reinstatement works. The Contractor is to allow for the daily testing and recording of moisture in structural materials, using electrical resistance or calcium carbide methods. All floor testing must be completed using the hygrometer test as per BS 8204-1. All testing results to be shared with the Contract Administrator. Price for each section below:1Itesting1.029Section 1 ditto1Ite1.030Section 2 ditto1Ite1.031Section 3 ditto1Ite1.032Section 4 ditto1Ite1.033The building has undergone a period of open drying. The Contractor is to allow for a minimum of 5 days of targeted or general mechanical drying to all retained ground-floor level floors and walls to achieve the agreed drying goals. The progress towards the drying goal is to be monitored and shared with the Contract Administrator. New finishes are only to be installed when the drying goal has been achieved or by agreement with the Contract Administrator. Price for each section below:1Ite1.034Section 1 ditto1Ite1.035Section 2 ditto1Ite1.036Section 3 ditto1Ite	. = =			
methods. All floor testing must be completed using the hygrometer test as per BS 8204-1. All testing results to be shared with the Contract Administrator. Price for each section below:1Itesting results to1.029Section 1 ditto1Ite1.030Section 2 ditto1Ite1.031Section 3 ditto1Ite1.032Section 4 ditto1Ite1.033The building has undergone a period of open drying. The Contractor is to allow for a minimum of 5 days of targeted or general mechanical drying to all retained ground-floor level floors and walls to achieve the agreed drying goals. The progress towards the drying goal is to be monitored and shared with the Contract Administrator. New finishes are only to be installed when the drying goal has been achieved or by agreement with the Contract Administrator. Price for each section below:1Ite1.034Section 1 ditto1Ite1.035Section 2 ditto1Ite1.036Section 3 ditto1Ite				
be shared with the Contract Administrator. Price for each section below:11.029Section 1 ditto11.030Section 2 ditto11.031Section 3 ditto11.032Section 4 ditto11.033The building has undergone a period of open drying. The Contractor is to allow for a minimum of 5 days of targeted or general mechanical drying to all retained ground-floor level floors and walls to achieve the agreed drying goals. The progress towards the drying goal is to be monitored and shared with the Contract Administrator. New finishes are only to be installed when the drying goal has been achieved or by agreement with the Contract Administrator. Price for each section below:11.034Section 1 ditto1Itte1.035Section 2 ditto1Itte1.036Section 3 ditto1Itte		the daily testing and recording of moisture in structural materials, using electrical resistance or calcium carbide		
1.029Section 1 ditto11 tr1.030Section 2 ditto11 tr1.031Section 2 ditto11 tr1.032Section 3 ditto11 tr1.033The building has undergone a period of open drying. The Contractor is to allow for a minimum of 5 days of targeted or general mechanical drying to all retained ground-floor level floors and walls to achieve the agreed drying goals. The progress towards the drying goal is to be monitored and shared with the Contract Administrator. New finishes are only to be installed when the drying goal has been achieved or by agreement with the Contract Administrator. Price for each section below:11 tr1.034Section 1 ditto11 tr1.035Section 2 ditto11 tr		methods. All floor testing must be completed using the hygrometer test as per BS 8204-1. All testing results to		
1.030Section 2 ditto1Ittel1.031Section 3 ditto1Ittel1.032Section 4 ditto1Ittel1.033The building has undergone a period of open drying. The Contractor is to allow for a minimum of 5 days of targeted or general mechanical drying to all retained ground-floor level floors and walls to achieve the agreed drying goals. The progress towards the drying goal is to be monitored and shared with the Contract Administrator. New finishes are only to be installed when the drying goal has been achieved or by agreement with the Contract Administrator. Price for each section below:1Ittel1.034Section 1 ditto1Ittel1.035Section 2 ditto1Ittel1.036Section 3 ditto1Ittel		be shared with the Contract Administrator. Price for each section below:		
1.030Section 2 ditto1Ittel1.031Section 3 ditto1Ittel1.032Section 4 ditto1Ittel1.033The building has undergone a period of open drying. The Contractor is to allow for a minimum of 5 days of targeted or general mechanical drying to all retained ground-floor level floors and walls to achieve the agreed drying goals. The progress towards the drying goal is to be monitored and shared with the Contract Administrator. New finishes are only to be installed when the drying goal has been achieved or by agreement with the Contract Administrator. Price for each section below:1Ittel1.034Section 1 ditto1Ittel1.035Section 2 ditto1Ittel1.036Section 3 ditto1Ittel				
1.031Section 3 ditto1Ite1.032Section 4 ditto1Ite1.033The building has undergone a period of open drying. The Contractor is to allow for a minimum of 5 days of drying goals. The progress towards the drying goal is to be monitored and shared with the Contract Administrator. New finishes are only to be installed when the drying goal has been achieved or by agreement with the Contract Administrator. Price for each section below:1Ite1.034Section 1 ditto1Ite1.035Section 2 ditto1Ite	1.029	Section 1 ditto	1	Item
1.032Section 4 ditto1Ite1.033The building has undergone a period of open drying. The Contractor is to allow for a minimum of 5 days of targeted or general mechanical drying to all retained ground-floor level floors and walls to achieve the agreed drying goals. The progress towards the drying goal is to be monitored and shared with the Contract Administrator. New finishes are only to be installed when the drying goal has been achieved or by agreement with the Contract Administrator. Price for each section below:1Ite1.034Section 1 ditto1Ite1.035Section 2 ditto1Ite	1.030	Section 2 ditto	1	Item
L.033The building has undergone a period of open drying. The Contractor is to allow for a minimum of 5 days of targeted or general mechanical drying to all retained ground-floor level floors and walls to achieve the agreed drying goals. The progress towards the drying goal is to be monitored and shared with the Contract Administrator. New finishes are only to be installed when the drying goal has been achieved or by agreement with the Contract Administrator. Price for each section below:1Itte1.034Section 1 ditto1Itte1.035Section 2 ditto1Itte	1.031	Section 3 ditto	1	Item
targeted or general mechanical drying to all retained ground-floor level floors and walls to achieve the agreed drying goals. The progress towards the drying goal is to be monitored and shared with the Contract Administrator. New finishes are only to be installed when the drying goal has been achieved or by agreement with the Contract Administrator. Price for each section below:1Ite1.034Section 1 ditto1Ite1.035Section 2 ditto1Ite1.036Section 3 ditto1Ite	1.032	Section 4 ditto	1	Item
drying goals. The progress towards the drying goal is to be monitored and shared with the Contract Administrator. New finishes are only to be installed when the drying goal has been achieved or by agreement uith the Contract Administrator. Price for each section below: 1.034 Section 1 ditto 1.035 Section 2 ditto 1.036 Section 3 ditto	1.033			
Administrator. New finishes are only to be installed when the drying goal has been achieved or by agreement with the Contract Administrator. Price for each section below:111.034Section 1 ditto11111.035Section 2 ditto11111.036Section 3 ditto1111			section below	
with the Contract Administrator. Price for each section below: 1 1.034 Section 1 ditto 1 1.035 Section 2 ditto 1 1.036 Section 3 ditto 1				
.034 Section 1 ditto 1 1 tr .035 Section 2 ditto 1 1 tr .036 Section 3 ditto 1 1 tr				
Section 2 ditto 1 1tr 1.036 Section 3 ditto 1 1tr		with the Contract Administrator. Price for each section below:		
1.036 Section 3 ditto 1 Ite	1.034	Section 1 ditto	1	Item
	1.035	Section 2 ditto	1	Item
1.037 Section 4 ditto 1 lite	1.036	Section 3 ditto	1	Item
	1.037	Section 4 ditto	1	ltem



		QUANT	UNIT
1.038	Prior to carrying out any reinstatement works, the Contractor is establish cleaning goals for the areas affected		
	by flooding, using the survey document provided in Appendix C1. Price here for completing the survey	section below	
	document provided in Appendix C1. Do not price here for cleaning works or for completing document on		
	completion. Cleaning of the affected areas of the buildings has already been carried out by others following		
	the initial flooding. Price for each section below:		
1.039	Section 1 ditto	1	Item
1.040	Section 2 ditto	1	Item
1.041	Section 3 ditto	1	Item
1.042	Section 4 ditto	1	Item
1.043	Flood reinstatement works		
1.044	Note: Laying of any floor finishes to be taken as acceptance of responsibility by main contractor and sub floor		
	contractor that the floor & preparation of the sub floor is suitable in every way to receive the intended floor		
	finish. Allow for self levelling latex screed to floor up to depth of 5mm. Greater than 5mm should be sand/		
	cement & screed, or ply deck build up to meet adjoining floor finish as indicated on the drawings contained in		
	Appendix B2. Allow for modifying any existing floor hatches or new, to suit surrounding floor finish.		
1.045	Note: All stud partitions and linings are to be installed in accordance with the British Gypsum White Book		
	recommendations including tape, joint, fill, sand and drywall top coat to leave a smooth surface suitable for		
	decoration. Angles, junctions, abutments, scribing, fair ends and angle bead etc. are to be included in the rate.		
	Boarding to fire compartment walls is to extend full height to underside of soffit and include all fire stopping to		
	service penetrations.		
1.046	Note: All new services passing through fire barriers to be wrapped or sleeved to provide fire protection as		
	required. Remedial works to building fabric to achieve resistance to be agreed on site. All new walls to		
	complete in accordance with BS and Approved Documents. All new wall linings are to achieve a classification B-		
	s1,d0 when tested in accordance with BS EN 13501. Existing walls and ceilings retained. Ceiling and wall		
	junctions to fire-resistant rooms to be installed to manufacturers recommendations. All new plasterboard walls		
	and ceilings to be British Gypsum plasterboard to BS requirements.		
1.047	Fire Doors		
1.048	Contractor's Design Portion: The Contractor is to design and replace existing fire doors within the ground floor	Doors	
	to match existing. Clear opening widths to match existing on site. Replacement doors as shown in Appendix B2	individually	
	and Appendix B3 - Door Schedule. Doors to be individually priced below with reference to both Appendix B2	priced below	
	and B3. Note that RAL colours are proposed only, the Contractor is to verify all colours, dimensions and	priced below	
		priced below	
	and B3. Note that RAL colours are proposed only, the Contractor is to verify all colours, dimensions and ironmongery specification on site. Clear opening dimensions to be as per existing dimensions on site.		
	and B3. Note that RAL colours are proposed only, the Contractor is to verify all colours, dimensions and ironmongery specification on site. Clear opening dimensions to be as per existing dimensions on site. - FD1 (Section 2)	1	Item
1.050	and B3. Note that RAL colours are proposed only, the Contractor is to verify all colours, dimensions and ironmongery specification on site. Clear opening dimensions to be as per existing dimensions on site. - FD1 (Section 2) - FD2 (Section 2)	 	Item
1.050 1.051	and B3. Note that RAL colours are proposed only, the Contractor is to verify all colours, dimensions and ironmongery specification on site. Clear opening dimensions to be as per existing dimensions on site. - FD1 (Section 2) - FD2 (Section 2) - FD3 (Section 1)	1 1 1	ltem Item
1.050 1.051 1.052	and B3. Note that RAL colours are proposed only, the Contractor is to verify all colours, dimensions and ironmongery specification on site. Clear opening dimensions to be as per existing dimensions on site. - FD1 (Section 2) - FD2 (Section 2) - FD3 (Section 1) - FD4 (Section 1)	1 1 1 1 1	Item Item Item
1.050 1.051 1.052 1.053	and B3. Note that RAL colours are proposed only, the Contractor is to verify all colours, dimensions and ironmongery specification on site. Clear opening dimensions to be as per existing dimensions on site. - FD1 (Section 2) - FD2 (Section 2) - FD3 (Section 1) - FD4 (Section 1) - FD5 (Section 1)	1 1 1 1 1 1 1	Item Item Item Item
1.050 1.051 1.052 1.053 1.054	and B3. Note that RAL colours are proposed only, the Contractor is to verify all colours, dimensions and ironmongery specification on site. Clear opening dimensions to be as per existing dimensions on site. - FD1 (Section 2) - FD2 (Section 2) - FD3 (Section 1) - FD4 (Section 1) - FD5 (Section 1) - FD6 (Section 1)	1 1 1 1 1 1 1 1 1	Item Item Item Item Item
1.050 1.051 1.052 1.053 1.054 1.055	and B3. Note that RAL colours are proposed only, the Contractor is to verify all colours, dimensions and ironmongery specification on site. Clear opening dimensions to be as per existing dimensions on site. - FD1 (Section 2) - FD2 (Section 2) - FD3 (Section 1) - FD4 (Section 1) - FD5 (Section 1) - FD6 (Section 1) - FD7 (Section 1)	1 1 1 1 1 1 1 1 1 1 1	Item Item Item Item Item
1.050 1.051 1.052 1.053 1.054 1.055 1.056	and B3. Note that RAL colours are proposed only, the Contractor is to verify all colours, dimensions and ironmongery specification on site. Clear opening dimensions to be as per existing dimensions on site. - FD1 (Section 2) - FD2 (Section 2) - FD3 (Section 1) - FD4 (Section 1) - FD5 (Section 1) - FD6 (Section 1) - FD6 (Section 1) - FD7 (Section 1) - FD8 (Section 1)	1 1 1 1 1 1 1 1 1 1 1 1 1	Item Item Item Item Item Item
1.050 1.051 1.052 1.053 1.054 1.055 1.056 1.057	and B3. Note that RAL colours are proposed only, the Contractor is to verify all colours, dimensions and ironmongery specification on site. Clear opening dimensions to be as per existing dimensions on site. - FD1 (Section 2) - FD2 (Section 2) - FD3 (Section 1) - FD4 (Section 1) - FD5 (Section 1) - FD6 (Section 1) - FD6 (Section 1) - FD7 (Section 1) - FD8 (Section 1) - FD8 (Section 1) - FD9 (Section 1)	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	Item Item Item Item Item Item Item
1.050 1.051 1.052 1.053 1.054 1.055 1.056 1.057 1.058	and B3. Note that RAL colours are proposed only, the Contractor is to verify all colours, dimensions and ironmongery specification on site. Clear opening dimensions to be as per existing dimensions on site. - FD1 (Section 2) - FD2 (Section 2) - FD3 (Section 1) - FD4 (Section 1) - FD5 (Section 1) - FD6 (Section 1) - FD6 (Section 1) - FD7 (Section 1) - FD8 (Section 1) - FD9 (Section 1) - FD9 (Section 1) - FD10 (Section 1)	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	Item Item Item Item Item Item Item
1.050 1.051 1.052 1.053 1.054 1.055 1.056 1.057 1.058 1.059	and B3. Note that RAL colours are proposed only, the Contractor is to verify all colours, dimensions and ironmongery specification on site. Clear opening dimensions to be as per existing dimensions on site. - FD1 (Section 2) - FD2 (Section 2) - FD3 (Section 1) - FD4 (Section 1) - FD5 (Section 1) - FD5 (Section 1) - FD6 (Section 1) - FD7 (Section 1) - FD8 (Section 1) - FD9 (Section 1) - FD10 (Section 1) - FD11 (Section 1)	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	Item Item Item Item Item Item Item Item
1.050 1.051 1.052 1.053 1.054 1.055 1.056 1.057 1.058 1.059 1.060	and B3. Note that RAL colours are proposed only, the Contractor is to verify all colours, dimensions and ironmongery specification on site. Clear opening dimensions to be as per existing dimensions on site. - FD1 (Section 2) - FD2 (Section 2) - FD3 (Section 1) - FD4 (Section 1) - FD5 (Section 1) - FD5 (Section 1) - FD6 (Section 1) - FD7 (Section 1) - FD8 (Section 1) - FD9 (Section 1) - FD10 (Section 1) - FD11 (Section 1) - FD12 (Section 1)	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	Item Item Item Item Item Item Item Item
1.050 1.051 1.052 1.053 1.054 1.055 1.056 1.057 1.058 1.059 1.060 1.061	and B3. Note that RAL colours are proposed only, the Contractor is to verify all colours, dimensions and ironmongery specification on site. Clear opening dimensions to be as per existing dimensions on site. - FD1 (Section 2) - FD2 (Section 2) - FD3 (Section 1) - FD4 (Section 1) - FD5 (Section 1) - FD5 (Section 1) - FD6 (Section 1) - FD7 (Section 1) - FD8 (Section 1) - FD9 (Section 1) - FD10 (Section 1) - FD11 (Section 1) - FD12 (Section 1) - FD13 (Section 1)	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	Item Item Item Item Item Item Item Item
1.050 1.051 1.052 1.053 1.054 1.055 1.056 1.057 1.058 1.059 1.060 1.061 1.062	and B3. Note that RAL colours are proposed only, the Contractor is to verify all colours, dimensions and ironmongery specification on site. Clear opening dimensions to be as per existing dimensions on site. - FD1 (Section 2) - FD2 (Section 2) - FD3 (Section 1) - FD4 (Section 1) - FD5 (Section 1) - FD5 (Section 1) - FD6 (Section 1) - FD7 (Section 1) - FD7 (Section 1) - FD9 (Section 1) - FD10 (Section 1) - FD11 (Section 1) - FD12 (Section 1) - FD13 (Section 1) - FD14 (Section 1)	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	Item Item Item Item Item Item Item Item
1.050 1.051 1.052 1.053 1.054 1.055 1.056 1.057 1.058 1.059 1.060 1.061 1.062 1.063	and B3. Note that RAL colours are proposed only, the Contractor is to verify all colours, dimensions and ironmongery specification on site. Clear opening dimensions to be as per existing dimensions on site. - FD1 (Section 2) - FD2 (Section 2) - FD3 (Section 1) - FD4 (Section 1) - FD5 (Section 1) - FD5 (Section 1) - FD6 (Section 1) - FD7 (Section 1) - FD8 (Section 1) - FD9 (Section 1) - FD10 (Section 1) - FD11 (Section 1) - FD12 (Section 1) - FD13 (Section 1) - FD14 (Section 1) - FD14 (Section 1) - FD15 (Section 1)	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	Item Item Item Item Item Item Item Item
1.050 1.051 1.052 1.053 1.054 1.055 1.056 1.057 1.058 1.059 1.060 1.061 1.062 1.063 1.064	and B3. Note that RAL colours are proposed only, the Contractor is to verify all colours, dimensions and ironmongery specification on site. Clear opening dimensions to be as per existing dimensions on site. - FD1 (Section 2) - FD2 (Section 2) - FD3 (Section 1) - FD4 (Section 1) - FD5 (Section 1) - FD5 (Section 1) - FD6 (Section 1) - FD7 (Section 1) - FD8 (Section 1) - FD9 (Section 1) - FD10 (Section 1) - FD11 (Section 1) - FD12 (Section 1) - FD13 (Section 1) - FD14 (Section 1) - FD14 (Section 1) - FD15 (Section 1) - FD15 (Section 1) - FD16 (Section 1) - FD16 (Section 1)	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	Item Item Item Item Item Item Item Item
1.050 1.051 1.052 1.053 1.054 1.055 1.056 1.057 1.058 1.060 1.061 1.062 1.063 1.064 1.065	and B3. Note that RAL colours are proposed only, the Contractor is to verify all colours, dimensions and ironmongery specification on site. Clear opening dimensions to be as per existing dimensions on site. - FD1 (Section 2) - FD2 (Section 2) - FD3 (Section 1) - FD4 (Section 1) - FD5 (Section 1) - FD5 (Section 1) - FD6 (Section 1) - FD7 (Section 1) - FD8 (Section 1) - FD9 (Section 1) - FD10 (Section 1) - FD11 (Section 1) - FD12 (Section 1) - FD13 (Section 1) - FD14 (Section 1) - FD14 (Section 1) - FD15 (Section 1) - FD15 (Section 1) - FD16 (Section 1) - FD17 (Section 1) - FD17 (Section 1)	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	Item Item Item Item Item Item Item Item
1.050 1.051 1.052 1.053 1.054 1.055 1.056 1.057 1.058 1.060 1.061 1.062 1.063 1.064 1.065 1.066	and B3. Note that RAL colours are proposed only, the Contractor is to verify all colours, dimensions and ironmongery specification on site. Clear opening dimensions to be as per existing dimensions on site. - FD1 (Section 2) - FD2 (Section 2) - FD3 (Section 1) - FD4 (Section 1) - FD5 (Section 1) - FD5 (Section 1) - FD6 (Section 1) - FD7 (Section 1) - FD8 (Section 1) - FD10 (Section 1) - FD10 (Section 1) - FD11 (Section 1) - FD11 (Section 1) - FD13 (Section 1) - FD14 (Section 1) - FD14 (Section 1) - FD15 (Section 1) - FD15 (Section 1) - FD16 (Section 1) - FD17 (Section 1) - FD18 (Section 1) - FD18 (Section 1) - FD19 (Section 2) - FD19	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	Item Item Item Item Item Item Item Item
1.050 1.051 1.052 1.053 1.054 1.055 1.056 1.057 1.058 1.060 1.061 1.063 1.064 1.065 1.066 1.067	and B3. Note that RAL colours are proposed only, the Contractor is to verify all colours, dimensions and ironmongery specification on site. Clear opening dimensions to be as per existing dimensions on site. - FD1 (Section 2) - FD2 (Section 2) - FD3 (Section 1) - FD4 (Section 1) - FD5 (Section 1) - FD5 (Section 1) - FD6 (Section 1) - FD7 (Section 1) - FD7 (Section 1) - FD8 (Section 1) - FD1 (Section 1) - FD1 (Section 1) - FD12 (Section 1) - FD13 (Section 1) - FD14 (Section 1) - FD14 (Section 1) - FD15 (Section 1) - FD15 (Section 1) - FD16 (Section 1) - FD16 (Section 1) - FD17 (Section 1) - FD16 (Section 1) - FD16 (Section 1) - FD17 (Section 1) - FD17 (Section 1) - FD18 (Section 1) - FD19 (Section 1)	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	Item Item Item Item Item Item Item Item
1.050 1.051 1.052 1.053 1.054 1.055 1.056 1.057 1.060 1.061 1.063 1.064 1.065 1.066 1.067 1.068	and B3. Note that RAL colours are proposed only, the Contractor is to verify all colours, dimensions and ironmongery specification on site. Clear opening dimensions to be as per existing dimensions on site. - FD1 (Section 2) - FD2 (Section 2) - FD3 (Section 1) - FD4 (Section 1) - FD5 (Section 1) - FD5 (Section 1) - FD6 (Section 1) - FD7 (Section 1) - FD8 (Section 1) - FD9 (Section 1) - FD1 (Section 1) - FD1 (Section 1) - FD12 (Section 1) - FD12 (Section 1) - FD13 (Section 1) - FD14 (Section 1) - FD15 (Section 1) - FD15 (Section 1) - FD16 (Section 1) - FD16 (Section 1) - FD17 (Section 1) - FD16 (Section 1) - FD16 (Section 1) - FD17 (Section 1) - FD19 (Section 1)	1 1 1 1 1 1 1 1 1 1 1 1 1 1	Item Item Item Item Item Item Item Item
1.050 1.051 1.052 1.053 1.054 1.055 1.056 1.057 1.060 1.061 1.062 1.063 1.064 1.065 1.066 1.067 1.068 1.069	and B3. Note that RAL colours are proposed only, the Contractor is to verify all colours, dimensions and ironmongery specification on site. Clear opening dimensions to be as per existing dimensions on site. - FD1 (Section 2) - FD2 (Section 2) - FD3 (Section 1) - FD4 (Section 1) - FD5 (Section 1) - FD5 (Section 1) - FD6 (Section 1) - FD7 (Section 1) - FD7 (Section 1) - FD8 (Section 1) - FD10 (Section 1) - FD11 (Section 1) - FD13 (Section 1) - FD14 (Section 1) - FD14 (Section 1) - FD15 (Section 1) - FD15 (Section 1) - FD15 (Section 1) - FD16 (Section 1) - FD17 (Section 1) - FD17 (Section 1) - FD18 (Section 1) - FD19 (1 1 1 1 1 1 1 1 1 1 1 1 1 1	Item Item Item Item Item Item Item Item
1.050 1.051 1.052 1.053 1.055 1.056 1.057 1.058 1.060 1.061 1.063 1.064 1.065 1.066 1.067 1.068 1.069 1.070	and B3. Note that RAL colours are proposed only, the Contractor is to verify all colours, dimensions and ironmongery specification on site. Clear opening dimensions to be as per existing dimensions on site. - FD1 (Section 2) - FD2 (Section 2) - FD3 (Section 1) - FD4 (Section 1) - FD5 (Section 1) - FD5 (Section 1) - FD5 (Section 1) - FD7 (Section 1) - FD7 (Section 1) - FD9 (Section 1) - FD10 (Section 1) - FD11 (Section 1) - FD11 (Section 1) - FD13 (Section 1) - FD13 (Section 1) - FD14 (Section 1) - FD15 (Section 1) - FD15 (Section 1) - FD16 (Section 1) - FD17 (Section 1) - FD19 (1 1 1 1 1 1 1 1 1 1 1 1 1 1	Item Item Item Item Item Item Item Item
1.050 1.051 1.052 1.053 1.055 1.056 1.057 1.058 1.060 1.061 1.062 1.063 1.064 1.065 1.066 1.067 1.068 1.069 1.070 1.071	and B3. Note that RAL colours are proposed only, the Contractor is to verify all colours, dimensions and ironmongery specification on site. Clear opening dimensions to be as per existing dimensions on site. - FD1 (Section 2) - FD2 (Section 1) - FD3 (Section 1) - FD4 (Section 1) - FD5 (Section 1) - FD5 (Section 1) - FD5 (Section 1) - FD7 (Section 1) - FD7 (Section 1) - FD9 (Section 1) - FD10 (Section 1) - FD10 (Section 1) - FD11 (Section 1) - FD13 (Section 1) - FD13 (Section 1) - FD14 (Section 1) - FD15 (Section 1) - FD15 (Section 1) - FD16 (Section 1) - FD17 (Section 1) - FD18 (Section 1) - FD19 (Section 1) - FD20 (Section 1) - FD20 (Section 1) - FD20 (Section 1) - FD21 (Section 1) - FD21 (Section 1) - FD23 (Section 1) - FD24 (Section 1) - FD24 (Section 1) - FD25 (Section 1) - FD25 (Section 1) - FD25 (Section 1) - FD26 (Section 1) - FD26 (Section 1) - FD27 (Section 1) - FD27 (Section 1) - FD28 (Section 1) - FD28 (Section 1) - FD28 (Section 1) - FD29 (Section 1) - FD29 (Section 1) - FD29 (1 1 1 1 1 1 1 1 1 1 1 1 1 1	Item Item Item Item Item Item Item Item
1.055 1.057 1.057 1.059 1.060 1.061 1.062 1.063 1.064 1.065 1.066 1.067 1.068 1.069 1.070	and B3. Note that RAL colours are proposed only, the Contractor is to verify all colours, dimensions and ironmongery specification on site. Clear opening dimensions to be as per existing dimensions on site. - FD1 (Section 2) - FD2 (Section 2) - FD3 (Section 1) - FD4 (Section 1) - FD5 (Section 1) - FD5 (Section 1) - FD5 (Section 1) - FD7 (Section 1) - FD7 (Section 1) - FD9 (Section 1) - FD10 (Section 1) - FD11 (Section 1) - FD11 (Section 1) - FD13 (Section 1) - FD13 (Section 1) - FD14 (Section 1) - FD15 (Section 1) - FD15 (Section 1) - FD16 (Section 1) - FD17 (Section 1) - FD19 (1 1 1 1 1 1 1 1 1 1 1 1 1 1	Item Item Item Item Item Item Item Item



ITEM		QUANT	UNIT
1.075	- FD29 (Section 4)	1	Item
1.076	- FD30 (Section 4)	1	Item
1.077	- FD31 (Section 3)	1	Item
1.078	- FD32 (Section 3)	1	Item
1.079	- FD33 (Section 3)	1	Item
1.080	External Doors		
1.081	The Contractor is to realign, prepare, prime and decorate previously painted external doors as shown in Appendix B2 and Appendix B3 - Door Schedule. Doors to be individually priced below with reference to both Appendix B2, B3 and B6. Note that RAL colours are proposed only, the Contractor is to verify all colours, dimensions and ironmongery specification on site. Decoration to include one coat of primer, two undercoats and one coat of gloss paint, colour: to match existing. Prepare and apply in accordance with manufacturer's recommendations.	Doors individually priced below	
1.082	- DR01 (Section 1):	1	Item
1.083	- DR02 (Section 1)	1	Item
1.084	- DR03 (Section 1)	1	Item
1.085	- DR04 (Section 1)	1	Item
1.086	- DR05 (Section 2)	1	Item
1.087	- DR06 (Section 2)	1	ltem
1.087	- DR07 (Section 2)	1	ltem
1.088	- DR07 (Section 1)	1	
1.089		1	ltem
1.090	- DR11 (Section 3)	T	Item
1.091	SECTION 1: Mill 1 - Reception area and corridors (Communal) Note: For the avoidance of doubt, the specification items in this section relate to all ground floor internal areas not contained within a named unit, including corridors, cleaner's cupboards, storage rooms kitchenettes, stairwells and elevator lobbies.		
1.093	Note: The lift lobby accessible from the Yard is not shown on the drawings.		
1.094	Contractor's Design Portion: Design and replace front reception counter laminated board panels to match existing. Desk worktop surface and 'Reception' signage to be retained.	1	Item
1.095	Contractor's Design Portion: Design and adapt the existing electrical installations in the communal reception areas and corridors only to provide future flood resilience and minimise risk of damage. Low level sockets to be repositioned at a height above finished floor level to minimise future flood damage (up to maximum height of 1650mm). All new conduits to be galvanised steel or PVC to avoid corrosion. All works to be Part M compliant and certification provided.	1	ltem
1.096	Hack off existing plaster and plasterboard and carefully remove other wall finishes from masonry walls, including paint, to a height of 1500mm, or 300mm above tide mark. Ensure walls are dry and prepared to receive new finishes, including removal of loose and friable material. Traces of gypsum plaster, bitumen or other materials to be removed. Make good any cracks, holes or imperfections. Works are to include temporary removal of fixtures and fittings. PROVISIONAL QUANTITY.	222	m²
1.097	Prime walls and apply Limelite Renovating Plaster or equivalent to masonry walls, following manufacturer's instructions. To be finished with skim coat of Limelite High Impact Finishing Plaster or equivalent. Plastered walls to achieve Level 3 finish according to BS EN 13914-2. Application of plaster only required to areas where previously removed and as indicated in Appendix B2 Proposed Drawings. To include reinstatement of fixtures and fittings. PROVISIONAL QUANTITY.	222	m²
1.098	Carefully remove and cart away plasterboard from both sides of all internal partition walls. Remove and cartaway any wet and damp plasterboard and insulation. Inspect timber framework for signs of rot or water damage and clean off any flood residue. Locations as indicated in Appendix B2 Proposed Drawings. To include temporary removal of fixtures and fittings. PROVISIONAL QUANTITY.	230	m²
1.099	Provisional sum (defined): Allow the provisional sum of £1,500.00 to replace damaged or rotten timber within internal partition walls	1	SUM
1.100	Provisional sum (defined): Allow the provisional sum of £1,000.00 to replace damaged or wet insulation within internal partition walls	1	SUM
1.101	Install new 12.5mm British gypsum plasterboard to both sides of internal wall partitions following BS requirements and joint into existing finishes to match existing up to a height of 3000mm. All to be installed as per manufacturers recommendations. Complete with corner and edge trims where required. Locations as indicated in Appendix B2 Proposed Drawings. Note: All locations are half hour fire rated requiring one layer of plasterboard on each elevation. Costs to include reinstatement of all fixtures and fittings affixed to walls. PROVISIONAL QUANTITY.	195	m
1.102	Supply and fix new skirting boards to all walls to match existing Style: Torus 18 x 169 mm. Locations as indicated in Appendix B2 Proposed Drawings. Painting of skirting boards allowed for in 1.86. PROVISIONAL QUANTITY.	130	m



ITEM		QUANT	UNIT
1.103	Prepare, prime and decorate all new softwood (e.g. door frames, architrave, trims, skirtings, window boards etc.) with one coat of primer, two undercoats and one coat of gloss paint, colour: Dulux Brilliant White Gloss Wood Paint. Prepare and apply in accordance with the specification & manufacturer's recommendations.	1	ltem
1.127b	Prime, prepare and decorate internal walls to ceiling height with one mist coat and two coats of Dulux Trade Diamond Matt Paint (Colour: Brilliant White) or equivalent breathable mineral- or water-based paint on agreement with the Contract Administrator. Preparation and application to follow manufacturers guidance and to BS 6150-6. Vinyl paints are not to be used. PROVISIONAL QUANTITY .	875	m²
#REF!	Contractor's Design Portion: The Contractor is to supply and install carpet tiles, laid to the manufacturer's instructions to two treads and risers of communal staircase to match existing colour. Existing nosing's to be retained.	1	ltem
1.106b	The Contractor is to supply and install INFINITY (product code: 34702) by Burmatex carpet tiles (https://www.burmatex.co.uk/contract-carpets/infinity-carpet-tiles/) to areas shown in Appendix B2. Carpet tiles will be from the manufacturer's standard colour range (colour: silver salt). One box to remain as spares. PROVISIONAL QUANTITY.	275	m²
#REF!	The Contractor is to procure and install Heckmondwike Battleship Heavy Contract Fibre Bonded Entrance Carpet to full area of glazed entrance vestibule (Colour: Anthracite). Entrance carpet to be provided with level FFL to other reception areas with carpet finish. To include aluminium threshold plates. All installed to manufacturers instructions and provided with manufacturer's 5 year warranty. SECTION 1: Mill 1 - Front Desk Kitchenette	1	ltem
#REF! #REF!	Remove and cart away vinyl floor finishes, including all trims. To include removal of all adhesives.	1	Item
#REF! #REF!	Provisional sum (defined): Allow the provisional sum of £400.00 to grind down and remove existing screeds.	1	SUM
#REF!	Provisional sum (defined): Allow the provisional sum of £800.00 to provide new moisture resistant chipboard C4(M) grade flooring where this is water damaged or above the drying goal described in Appendix C2 (Drying goals)	1	SUM
#REF!	Hack off existing plaster and plasterboard and carefully remove other wall finishes from walls, including paint, to a height of 1500mm or 300mm above tide mark. Ensure walls are dry and prepared to receive new finishes, including removal of loose and friable material. Traces of gypsum plaster, bitumen or other materials to be removed. Make good any cracks, holes or imperfections. To include temporary removal of fixtures and fittings. PROVISIONAL QUANTITY.	20	m²
#REF!	Prime walls and apply Limelite Renovating Plaster or equivalent to masonry walls, following manufacturer's instructions. To be finished with skim coat of Limelite High Impact Finishing Plaster or equivalent. Plastered walls to achieve Level 3 finish according to BS EN 13914-2. Application of plaster only required to areas where previously removed and as indicated in Appendix B2 Proposed Drawings. To include reinstatements of fixtures and fittings. PROVISIONAL QUANTITY.	33	m²
#REF!	Carefully remove and cart away plasterboard from both sides of all internal partition walls. Remove and cartaway any wet and damp plasterboard and insulation. Inspect timber framework for signs of rot or water damage and clean off any flood residue. Locations as indicated in Appendix B2 Proposed Drawings. To include temporary removal of fixtures and fittings. PROVISIONAL QUANTITY .	33	m²
#REF!	Provisional sum (defined): Allow the provisional sum of £1,500.00 to replace damaged or rotten timber within internal partition walls	1	SUM
#REF!	Provisional sum (defined): Allow the provisional sum of £1,000.00 to replace damaged or wet insulation within internal partition walls	1	SUM
#REF!	Provisional sum (defined): Allow the provisional sum of £400.00 to provide a minimum 5.5mm thickness plywood to provide a smooth and even finish. Flooring grade plywood such as Hanson SP101 or similar should be used. Refer to BS8203:2017 and Contract Flooring Association guidelines. All screwed and nail head fixings to finish below the surface of overlayed plywood and any indentations and joints in the plywood filled with an appropriate filler.	1	SUM
#REF!	Install new 12.5mm British gypsum plasterboard to both sides of internal wall partitions following BS requirements and joint into existing finishes to match existing up to a height of 3000mm. All to be installed as per manufacturers recommendations. Complete with corner and edge trims where required. Locations as indicated in Appendix B2 Proposed Drawings. Note: All locations are half hour fire rated requiring one layer of plasterboard on each elevation. Costs to include reinstatement of all fixtures and fittings affixed to walls. PROVISIONAL QUANTITY.	13	m
#REF!	The Contractor is to procure and install Altro Stronghold 30 [™] flooring, laid to the manufacturer's instructions within the locations identified on the drawings. Vinyl flooring will be from the manufacturer's standard colour range (colour Dolphin K3010). All weld rods in matching WR86 colour and AltroMastic 100 A1M86. Where necessary a levelling compound will be laid to achieve an even flat finish to the vinyl. Allow for all trims, threshold plates, cove formers etc. PROVISIONAL QUANTITY.	10	m²



ITEM		QUANT	UNIT
#REF!	All areas with Altro Stronghold 30 floor finish are to have 100mm coved vinyl skirting; capped coved skirting to be installed where the wall finish is plaster and painted finish. Aluminium edge trims are to be provided to all door thresholds.	1	item
1.121b	Prime, prepare and decorate internal walls to ceiling height with one mist coat and two coats of Dulux Trade Diamond Matt Paint (Colour: Brilliant White) or equivalent breathable mineral- or water-based paint on agreement with the Contract Administrator. Preparation and application to follow manufacturers guidance and to BS 6150-6. Vinyl paints are not to be used. PROVISIONAL QUANTITY	33	m²
#REF!	Prepare, prime and decorate all new and previously painted softwood (e.g. door frames, architrave, trims, skirtings, window boards etc.) with one coat of primer, two undercoats and one coat of gloss paint, colour: Dulux Brilliant White Gloss Wood Paint. Prepare and apply in accordance with the specification & manufacturer's recommendations.	1	ltem
#REF!	Contractor's Design Portion: Design and replace under sink cupboard unit and plinths to match existing. All units to be sealed.	1	Item
#REF!	SECTION 1: Mill 1 - WCs (Communal)		
#REF!	Hack off existing plaster and plasterboard and carefully remove other wall finishes from masonry walls, including paint, to a height of 1500mm or 300mm above tide mark. Ensure walls are dry and prepared to receive new finishes, including removal of loose and friable material. Traces of gypsum plaster, bitumen or other materials to be removed. Make good any cracks, holes or imperfections. To include temporary removal of fixtures and fittings. PROVISIONAL QUANTITY.	57	m²
#REF!	Prime walls and apply Limelite Renovating Plaster or equivalent to masonry walls, following manufacturer's instructions. To be finished with skim coat of Limelite High Impact Finishing Plaster or equivalent. Plastered walls to achieve Level 3 finish according to BS EN 13914-2. Application of plaster only required to areas where previously removed and as indicated in Appendix B2 Proposed Drawings. To include reinstatement of fixtures and fittings in previous positions. PROVISIONAL QUANTITY.	57	m²
1.127b	Prime, prepare and decorate internal walls to ceiling height with one mist coat and two coats of Dulux Trade Diamond Matt Paint (Colour: Brilliant White) or equivalent breathable mineral- or water-based paint on agreement with the Contract Administrator. Preparation and application to follow manufacturers guidance and to BS 6150-6. Vinyl paints are not to be used. PROVISIONAL QUANTITY	95	m²
#REF!	Prepare, prime and decorate all new and previously painted softwood (e.g. door frames, architrave, trims, skirtings, window boards etc.) with one coat of primer, two undercoats and one coat of gloss paint, colour: Dulux Brilliant White Gloss Wood Paint. Prepare and apply in accordance with the specification & manufacturer's recommendations.	1	ltem
#REF!	Remove and cart away vinyl floor finishes including all trims and adhesive. PROVISIONAL QUANTITY .	25	m²
#REF!	Grind down floors to remove any remaining adhesive and existing levelling screed. PROVISIONAL QUANTITY.	25	m²
#REF!	Provisional sum (defined): Allow the provisional sum of £250.00 to carry out repairs to floors prior to laying new finishes.	1	SUM
#REF!	The Contractor is to procure and install Altro Stronghold 30 [™] flooring, laid to the manufacturer's instructions within the locations identified on the drawings. Vinyl flooring will be from the manufacturer's standard colour range (colour Dolphin K3010). All weld rods in matching WR86 colour and AltroMastic 100 A1M86. Where necessary a levelling compound will be laid to achieve an even flat finish to the vinyl. Allow for all trims, threshold plates, cove formers etc. PROVISIONAL QUANTITY.	25	m²
#REF!	All areas with Altro Stronghold 30 floor finish are to have 100mm coved vinyl skirting; capped coved skirting to be installed where the wall finish is plaster and painted finish. Aluminium edge trims are to be provided to all door thresholds	1	ltem
#REF!	Contractor's Design Portion: Design and replace vanity units and plinths to same specification as existing. Retain all sinks, taps, plumbing etc. Apply sealant to all wall joints.	2	nr
#REF!	SECTION 1: Mill 1 - Cleaner's Cupboard (Communal)		
#REF!	Hack off existing plaster and plasterboard and carefully remove other wall finishes from masonry walls, including paint, to a height of 1500mm or 300mm above tide mark. Ensure walls are dry and prepared to receive new finishes, including removal of loose and friable material. Traces of gypsum plaster, bitumen or other materials to be removed. Make good any cracks, holes or imperfections. To include temporary removal of fixtures and fittings. PROVISIONAL QUANTITY.	18	m²
#REF!	Prime walls and apply Limelite Renovating Plaster or equivalent to masonry walls, following manufacturer's instructions. To be finished with skim coat of Limelite High Impact Finishing Plaster or equivalent. Plastered walls to achieve Level 3 finish according to BS EN 13914-2. Application of plaster only required to areas where previously removed and as indicated in Appendix B2 Proposed Drawings. To include reinstatement of fixtures and fittings. PROVISIONAL QUANTITY.	18	m²



ITEM		QUANT	UNIT
1.138b	Prime, prepare and decorate internal walls to ceiling height with one mist coat and two coats of Dulux Trade Diamond Matt Paint (Colour: Brilliant White) or equivalent breathable mineral- or water-based paint on agreement with the Contract Administrator. Preparation and application to follow manufacturers guidance and to BS 6150-6. Vinyl paints are not to be used. PROVISIONAL QUANTITY	28	m
#REF!	Uplift and cartaway existing ceramic floor tiles. PROVISIONAL QUANTITY.	8	m²
#REF!	Grind down floors to remove any remaining adhesive. PROVISIONAL QUANTITY.	8	m²
#REF!	The Contractor is to procure and install Dotti Corund R11 Slip Resistant Floor Tiles, laid to the manufacturer's instructions within the locations identified on the drawings. Colour: Ivory. Ardex Flex FL Tile Grout or equivalent to be used for all tile joints, Colour: White. Mastic to be applied at wall-to-floor joints. Where necessary a levelling compound will be laid to achieve an even flat finish. Allow for all trims and aluminium threshold plate. PROVISIONAL QUANTITY.	8	m²
#REF!	Supply and fix new skirting boards to all walls to match existing: Pencil Round 18 x 169 mm. Caulked to top edge. Locations as indicated in Appendix B2 Proposed Drawings. PROVISIONAL QUANTITY.	12	m
#REF!	Prepare, prime and decorate all new and previously painted softwood (e.g. door frames, architrave, trims, skirtings etc.) with one coat of primer, two undercoats and one coat of gloss paint, colour: Dulux Brilliant White Gloss Wood Paint. Prepare and apply in accordance with the specification & manufacturer's recommendations.	1	Item
#REF!	SECTION 2: Mill 1 - Unit EG (Meeting Room/Community Space)		
#REF!	Provisional sum (defined): Allow the provisional sum of £2,000.00 to overlay timber floors with new moisture resistant chipboard C4(M) grade flooring where this is water damaged.	1	SUM
#REF!	Provisional sum (defined): Allow the provisional sum of £4,000.00 to cut away rotting joist ends embedded in walls, repairing with treated timber extensions, supported on joist hangers. Treat adjacent timbers to reduce the risk of rot spreading. Treat wet but sound joist ends with preservative plugs.	1	SUM
#REF!	Provisional sum (defined): Allow the provisional sum of £2,000.00 to carry out sanding of floor joists to remove cupping. Sanding only to be carried out when flooring has been fully dried.	1	SUM
#REF!	Hack off existing plaster and plasterboard and carefully remove other wall finishes from masonry walls, including paint, to a height of 1500mm or 300mm above tide mark. Ensure walls are dry and prepared to receive new finishes, including removal of loose and friable material. Traces of gypsum plaster, bitumen or other materials to be removed. Make good any cracks, holes or imperfections. To include temporary removal of fixtures and fittings. PROVISIONAL QUANTITY.	55	m²
#REF!	Prime walls and apply Limelite Renovating Plaster or equivalent to masonry walls, following manufacturer's instructions. To be finished with skim coat of Limelite High Impact Finishing Plaster or equivalent. Plastered walls to achieve Level 3 finish according to BS EN 13914-2. Application of plaster only required to areas where previously removed and as indicated in Appendix B2 Proposed Drawings. To include reinstatement of fixtures and fittings. PROVISIONAL QUANTITY.	55	m²
#REF!	The Contractor is to supply and install INFINITY (product code: 34702) by Burmatex carpet tiles (https://www.burmatex.co.uk/contract-carpets/infinity-carpet-tiles/) to areas shown in Appendix B2. Carpet tiles will be from the manufacturer's standard colour range (colour: silver salt). PROVISIONAL QUANTITY.	30	m²
1.151b	Prime, prepare and decorate internal walls to ceiling height with one mist coat and two coats of Dulux Trade Diamond Matt Paint (Colour: Brilliant White) or equivalent breathable mineral- or water-based paint on agreement with the Contract Administrator. Preparation and application to follow manufacturers guidance and to BS 6150-6. Vinyl paints are not to be used. PROVISIONAL QUANTITY	110	m²
1.152b	Supply and fix new skirting boards to all walls to match existing Style: Torus 18 x 169 mm. Locations as indicated in Appendix B2 Proposed Drawings. Painting of skirting boards allowed for in 2.85. PROVISIONAL QUANTITY.	30	m
#REF!	Prepare, prime and decorate all new and previously painted softwood (e.g. door frames, architrave, trims, skirtings, window boards etc.) with one coat of primer, two undercoats and one coat of gloss paint, colour: Dulux Brilliant White Gloss Wood Paint. Prepare and apply in accordance with the specification & manufacturer's recommendations.	1	ltem
#REF!	SECTION 2: Mill 1 - Meeting Room/Community Space Kitchenette		
#REF!	Provisional sum (defined): Allow the provisional sum of £2,000.00 to sand and plane swollen floor joists to achieve level floor finish.	1	SUM
#REF!	Provisional sum (defined): Allow the provisional sum of £300.00 to provide new moisture resistant chipboard C4(M) grade flooring where this is water damaged.	1	SUM
#REF!	Provisional sum (defined): Allow the provisional sum of £200.00 to replace wet pipe insulation with close-cell material. Remove and replace wet mineral wall insulation.	1	SUM
#REF!	Contractor's Design Portion: Replace under sink cupboard unit and plinths on a like-for-like basis to same specification as existing. Mastic to be applied around all units.	1	Item



ITEM		QUANT	UNIT
#REF!	Hack off existing plaster and plasterboard and carefully remove other wall finishes from masonry walls, including paint, to a height of 1500mm or 300mm above tide mark. Ensure walls are dry and prepared to receive new finishes, including removal of loose and friable material. Traces of gypsum plaster, bitumen or other materials to be removed. Make good any cracks, holes or imperfections. To include temporary removal of fixtures and fittings. PROVISIONAL QUANTITY.	55	m²
#REF!	Prime walls and apply Limelite Renovating Plaster or equivalent to masonry walls, following manufacturer's instructions. To be finished with skim coat of Limelite High Impact Finishing Plaster or equivalent. Plastered walls to achieve Level 3 finish according to BS EN 13914-2. Application of plaster only required to areas where previously removed and as indicated in Appendix B2 Proposed Drawings. To include reinstatement of fixtures and fittings. PROVISIONAL QUANTITY.	55	m²
#REF!	The Contractor is to procure and install Altro Stronghold 30 [™] flooring, laid to the manufacturer's instructions within the locations identified on the drawings. Vinyl flooring will be from the manufacturer's standard colour range (colour Dolphin K3010). All weld rods in matching WR86 colour and AltroMastic 100 A1M86. Where necessary a levelling compound will be laid to achieve an even flat finish to the vinyl. Allow for all trims, threshold plates, cove formers etc. PROVISIONAL QUANTITY.	24	m²
#REF!	All areas with Altro Stronghold 30 floor finish are to have 100mm coved vinyl skirting; capped coved skirting to be installed where the wall finish is plaster and painted finish. Aluminium edge trims are to be provided to all door thresholds	1	ltem
1.163b	Prime, prepare and decorate internal walls to ceiling height with one mist coat and two coats of Dulux Trade Diamond Matt Paint (Colour: Brilliant White) or equivalent breathable mineral- or water-based paint on agreement with the Contract Administrator. Preparation and application to follow manufacturers guidance and to BS 6150-6. Vinyl paints are not to be used. PROVISIONAL QUANTITY	75	m²
#REF!	Prepare, prime and decorate all new and previously painted softwood (e.g. door frames, architrave, trims, skirtings, window boards etc.) with one coat of primer, two undercoats and one coat of gloss paint, colour: Dulux Brilliant White Gloss Wood Paint. Prepare and apply in accordance with the specification & manufacturer's recommendations.	1	ltem
#REF!	SECTION 1: Mill 1 - Unit AG (Tenant: Sylvan Enterprises of Sherwood Forest Ltd)		
#REF!	Carefully remove loose and flaking paint, to a height of 1500mm or 300mm above tide mark. Ensure walls are dry and prepared to receive new finishes, including removal of loose and friable material. Traces of gypsum plaster, bitumen or other materials to be removed. Removal of fixtures and fittings only required to prepare for decoration. PROVISIONAL QUANTITY.	200	m²
1.167b	Prime, prepare and decorate internal walls to ceiling height with one mist coat and two coats of Dulux Trade Diamond Matt Paint (Colour: Brilliant White) or equivalent breathable mineral- or water-based paint on agreement with the Contract Administrator. Preparation and application to follow manufacturers guidance and to BS 6150-6. Vinyl paints are not to be used. PROVISIONAL QUANTITY	200	m²
#REF!	Prepare, prime and decorate all new and previously painted softwood (e.g. door frames, architrave, trims, skirtings, window boards etc.) with one coat of primer, two undercoats and one coat of gloss paint, colour: Dulux Brilliant White Gloss Wood Paint. Prepare and apply in accordance with the specification & manufacturer's recommendations.	1	ltem
#REF!	SECTION 2: Mill 1 - Unit BG (Tenant: Bell Bespoke Interiors Ltd)		
#REF!	Note : Unit BG unit was only partially affected by flooding. Drawings in Appendix B2 should be referred to as an indication of areas where works are required.	Note	
#REF!	Hack off existing plaster and plasterboard and carefully remove other wall finishes from walls, including paint, to a height of 1500mm or 300mm above tide mark. Ensure walls are dry and prepared to receive new finishes, including removal of loose and friable material. Traces of gypsum plaster, bitumen or other materials to be removed. Make good any cracks, holes or imperfections. To include temporary removal of fixtures and fittings. PROVISIONAL QUANTITY.	40	m²
#REF!	Prime walls and apply Limelite Renovating Plaster or equivalent to masonry walls, following manufacturer's instructions. To be finished with skim coat of Limelite High Impact Finishing Plaster or equivalent. Plastered walls to achieve Level 3 finish according to BS EN 13914-2. Application of plaster only required to areas where previously removed and as indicated in Appendix B2 Proposed Drawings. To include reinstatements of fixtures and fittings. PROVISIONAL QUANTITY.	40	m²
#REF!	Carefully remove and cart away plasterboard from both sides of all internal partition walls. Remove and cartaway any wet and damp plasterboard and insulation. Inspect timber framework for signs of rot or water damage and clean off any flood residue. Locations as indicated in Appendix B2 Proposed Drawings. To include temporary removal of fixtures and fittings. PROVISIONAL QUANTITY.	30	m²
	Provisional sum (defined): Allow the provisional sum of £1,500.00 to replace damaged or rotten timber within	1	SUM
#REF!	internal partition walls	-	



ITEM		QUANT	UNIT
#REF!	Install new 12.5mm British gypsum plasterboard to both sides of internal wall partitions following BS requirements and joint into existing finishes to match existing up to a height of 3000mm. All to be installed as per manufacturers recommendations. Complete with corner and edge trims where required. Locations as indicated in Appendix B2 Proposed Drawings. Note: All locations are half hour fire rated requiring one layer of plasterboard on each elevation. Costs to include reinstatement of all fixtures and fittings affixed to walls. PROVISIONAL QUANTITY.	9	m
1.177b	Grind down floors to remove existing screed where this has failed in localised area. PROVISIONAL QUANTITY	60	m²
#REF!	Warehouse flooring where existing screed removed to be treated with a self-levelling screed to achieve SR2 Level Rating. Joint into existing screed and floor finishes. Specification: SikaScreed HardTop-60 or equivalent installed to manufacturers instructions. PROVISIONAL QUANTITY.	60	m²
1.179b	Contractor's Design Portion: Warehouse flooring where existing screed removed in Unit BG to be treated with an epoxy floor coating in colours and design to match existing. PROVISIONAL QUANTITY.	60	m²
1.180b	Prime, prepare and decorate internal walls to ceiling height with one mist coat and two coats of Dulux Trade Diamond Matt Paint (Colour: Brilliant White) or equivalent breathable mineral- or water-based paint on agreement with the Contract Administrator. Preparation and application to follow manufacturers guidance and to BS 6150-6. Vinyl paints are not to be used. PROVISIONAL QUANTITY	120	m²
1.181b	Supply and fix new skirting boards to all walls to match existing Style: Pencil Round 18 x 169 mm. Locations as indicated in Appendix B2 Proposed Drawings. Painting of skirting boards allowed for in separate item. PROVISIONAL QUANTITY.	15	m
#REF!	Prepare, prime and decorate all new and previously painted softwood (e.g. door frames, architrave, trims, skirtings, window boards etc.) with one coat of primer, two undercoats and one coat of gloss paint, colour: Dulux Brilliant White Gloss Wood Paint. Prepare and apply in accordance with the specification & manufacturer's recommendations.	1	Item
#REF!	SECTION 2: Mill 1 - Units DG, DG2 and CG (Tenant: Bladen Box Ltd)		
#REF!	Hack off existing plaster and plasterboard and carefully remove other wall finishes from walls, including paint, to a height of 1500mm or 300mm above tide mark. Ensure walls are dry and prepared to receive new finishes, including removal of loose and friable material. Traces of gypsum plaster, bitumen or other materials to be removed. Make good any cracks, holes or imperfections. To include temporary removal of fixtures and fittings. PROVISIONAL QUANTITY.	400	m²
#REF!	Prime walls and apply Limelite Renovating Plaster or equivalent to masonry walls, following manufacturer's instructions. To be finished with skim coat of Limelite High Impact Finishing Plaster or equivalent. Plastered walls to achieve Level 3 finish according to BS EN 13914-2. Application of plaster only required to areas where previously removed and as indicated in Appendix B2 Proposed Drawings. To include reinstatements of fixtures and fittings. PROVISIONAL QUANTITY.	255	m²
#REF!	Carefully remove and cart away plasterboard from both sides of all internal partition walls. Remove and cartaway any wet and damp plasterboard and insulation. Inspect timber framework for signs of rot or water damage and clean off any flood residue. Locations as indicated in Appendix B2 Proposed Drawings. To include temporary removal of fixtures and fittings. PROVISIONAL QUANTITY.	146	m²
#REF!	Provisional sum (defined): Allow the provisional sum of £1,500.00 to replace damaged or rotten timber within internal partition walls	1	SUM
#REF!	Provisional sum (defined): Allow the provisional sum of £1,000.00 to replace damaged or wet insulation within internal partition walls	1	SUM
#REF!	Install new 12.5mm British gypsum plasterboard to both sides of internal wall partitions following BS requirements and joint into existing finishes to match existing up to a height of 3000mm. All to be installed as per manufacturers recommendations. Complete with corner and edge trims where required. Locations as indicated in Appendix B2 Proposed Drawings. Note: All locations are half hour fire rated requiring one layer of plasterboard on each elevation. Costs to include reinstatement of all fixtures and fittings affixed to walls. PROVISIONAL QUANTITY.	98	m
#REF!	Prepare, prime and decorate all new and previously painted softwood (e.g. door frames, architrave, trims, skirtings, window boards etc.) with one coat of primer, two undercoats and one coat of gloss paint, colour: Dulux Brilliant White Gloss Wood Paint. Prepare and apply in accordance with the specification & manufacturer's recommendations.	1	ltem
#REF!	Supply and fix new skirting boards to all walls to match existing Style: Torus 18 x 169 mm. Locations as indicated in Appendix B2 Proposed Drawings. Painting of skirting boards allowed for in 2.85. PROVISIONAL QUANTITY.	20	m
1.192b	Prime, prepare and decorate internal walls to ceiling height with one mist coat and two coats of Dulux Trade Diamond Matt Paint (Colour: Brilliant White) or equivalent breathable mineral- or water-based paint on agreement with the Contract Administrator. Preparation and application to follow manufacturers guidance and to BS 6150-6. Vinyl paints are not to be used. PROVISIONAL QUANTITY	800	m²
#REF!	Contractor's Design Portion: Survey, design and replacement of broken external window to west elevation to match existing.	1	nr
#REF!	SECTION 1: Mill 1 - External		



ITEM		QUANT	UNIT
#REF!	Reinstate and level displaced rubberised external floor tiles to the west of the building. Install new tiles where missing to ensure full area is covered. New tiles to match existing. Level finished surface required.	1	ltem
#REF!	SECTION 3: Mill 2 - External		
#REF!	Contractor's Design Portion: Design and reinstate hardstanding and signpost which was washed away during flooding. Cart away any loose debris, including masonry and stonework, leaving the river bank free.	1	Item
#REF!	SECTION 3: Mill 3 - Unit RB		
#REF!	Relocate assets as detailed in Appendix D to the temporary stores on site. Return all assets upon completion of the works.	1	Item
#REF!	Repoint areas of missing or defective brickwork pointing up to a height of 1500mm using Limelite Heritage Lime Mortar or equivalent to match existing. Carefully rake out and remove any areas of loose and friable mortar between brickwork prior to application. All to manufacturers recommendations. PROVISIONAL QUANTITY.	40	m²
1.201b	Prime, prepare and decorate internal walls to ceiling height with one mist coat and two coats of Dulux Trade Diamond Matt Paint (Colour: Brilliant White) or equivalent breathable mineral- or water-based paint on agreement with the Contract Administrator. Preparation and application to follow manufacturers guidance and to BS 6150-6. Vinyl paints are not to be used. PROVISIONAL QUANTITY	270	m²
#REF!	Prepare, prime and decorate 6no. metal columns to full height in Dulux Trade Gloss, colour: RAL 9005. Remove any loose or flaking paint prior to decoration. Treat corrosion prior to application of new coatings.	6	Items
#REF!	Provisional sum (defined): Allow provisional sum of £800.00 to carry out repairs to damaged staircase to rear stairwell. Contractor will be required to remove warped or defective treads and risers, and either reinforce or replace them with materials and specification to match the original.	1	SUM
#REF!	SECTION 3: Mill 3 - Unit 31		
#REF!	Repoint areas of missing or defective brickwork pointing up to a height of 1500mm using Limelite Heritage Lime Mortar or equivalent. colour: Unity Ink Blue to match existing. Carefully rake out and remove any areas of loose and friable mortar between brickwork prior to application. All to manufacturers recommendations. PROVISIONAL QUANTITY.	40	m²
#REF!	Carefully remove and cart away plasterboard from both sides of all internal partition walls. Remove and cartaway any wet and damp plasterboard and insulation. Inspect timber framework for signs of rot or water damage and clean off any flood residue. Locations as indicated in Appendix B2 Proposed Drawings. To include temporary removal of fixtures and fittings. PROVISIONAL QUANTITY.	146	m²
#REF!	Provisional sum (defined): Allow the provisional sum of £1,500.00 to replace damaged or rotten timber within internal partition walls	1	SUM
#REF!	Provisional sum (defined): Allow the provisional sum of £1,000.00 to replace damaged or wet insulation within internal partition walls	1	SUM
#REF!	Install new 12.5mm British gypsum plasterboard to both sides of internal wall partitions following BS requirements and joint into existing finishes to match existing up to a height of 3000mm. All to be installed as per manufacturers recommendations. Complete with corner and edge trims where required. Locations as indicated in Appendix B2 Proposed Drawings. Note: All locations are half hour requiring one layer of plasterboard to each elevation. Costs to include reinstatement of all fixtures and fittings affixed to walls. PROVISIONAL QUANTITY.	98	m
#REF!	Supply and fix new skirting boards to all walls to match existing Style: Torus 18 x 169 mm. Locations as indicated in Appendix B2 Proposed Drawings. Painting of skirting boards allowed for in 2.85. PROVISIONAL QUANTITY.	15	m
#REF!	Prepare, prime and decorate all new and previously painted softwood (e.g. door frames, architrave, trims, skirtings, window boards etc.) with one coat of primer, two undercoats and one coat of gloss paint, colour: Dulux Brilliant White Gloss Wood Paint. Prepare and apply in accordance with the specification & manufacturer's recommendations.	1	ltem
1.213b	Prime, prepare and decorate internal walls to ceiling height with one mist coat and two coats of Dulux Trade Diamond Matt Paint (Colour: Brilliant White) or equivalent breathable mineral- or water-based paint on agreement with the Contract Administrator. Preparation and application to follow manufacturers guidance and to BS 6150-6. Vinyl paints are not to be used. PROVISIONAL QUANTITY	270	m²
#REF!	SECTION 3: Mill 3 - External		
#REF!	Carefully remove and cart away loose brickwork and debris from collapsed car park wall adjacent to and within the River Meden. Vegetation to be removed to prepare ground to receive new timber fencing. PROVISIONAL QUANTITY.	12	m



ITEM		QUANT	UNIT
#REF!	Contractor's Design Portion: Supply and install a 3-rail timber square post-and-rail fence to a height of 1500mm in accordance with BS1722-5 to continue existing timber fencing. Posts to be set in concrete. Fencing to be sawn square rails fixed to square posts. Maximum span between posts to be 1800mm. All cuts to receive treated end grain preservative. Fencing to provided with 25 year guarantee. Round reflectors installed facing car park. PROVISIONAL QUANTITY.	12	m
#REF!	Carefully remove and cart away existing defective timber fencing rails. Replace with sawn square rails fixed to existing square posts. All cuts to receive treated end grain preservative. PROVISIONAL QUANTITY.	20	m
#REF!	SECTION 4: Mill Court - Entrance Lobby		
#REF!	Hack off existing plaster and plasterboard and carefully remove other wall finishes from walls, including paint, to a height of 1500mm or 300mm above tide mark. Ensure walls are dry and prepared to receive new finishes, including removal of loose and friable material. Traces of gypsum plaster, bitumen or other materials to be removed. Make good any cracks, holes or imperfections. To include temporary removal of fixtures and fittings. PROVISIONAL QUANTITY.	25	m²
#REF!	Prime walls and apply Limelite Renovating Plaster or equivalent to masonry walls, following manufacturer's instructions. To be finished with skim coat of Limelite High Impact Finishing Plaster or equivalent. Plastered walls to achieve Level 3 finish according to BS EN 13914-2. Application of plaster only required to areas where previously removed and as indicated in Appendix B2 Proposed Drawings. To include reinstatements of fixtures and fittings. PROVISIONAL QUANTITY.	25	m²
1.221b	Prime, prepare and decorate internal walls to ceiling height with one mist coat and two coats of Dulux Trade Diamond Matt Paint (Colour: Brilliant White) or equivalent breathable mineral- or water-based paint on agreement with the Contract Administrator. Preparation and application to follow manufacturers guidance and to BS 6150-6. Vinyl paints are not to be used. PROVISIONAL QUANTITY	42	m²
#REF!	Supply and fix new skirting boards to all walls to match existing Style: Torus 18 x 169 mm. Locations as indicated in Appendix B2 Proposed Drawings. Painting of skirting boards allowed for in 2.85. PROVISIONAL QUANTITY.	18	m
#REF!	Prepare, prime and decorate all new softwood (e.g. door frames, architrave, trims, skirtings, window boards etc.) with one coat of primer, two undercoats and one coat of gloss paint, colour: Dulux Brilliant White Gloss Wood Paint. Prepare and apply in accordance with the specification & manufacturer's recommendations.	1	ltem
1.224b	Grind down floors to remove existing screed where this has failed in localised area. PROVISIONAL QUANTITY	17	m²
1.224c	Flooring where existing screed removed to be treated with a self-levelling screed to achieve SR2 Level Rating. Joint into existing screed and floor finishes. Specification: Ardex K15 HB or equivalent installed to manufacturers instructions. PROVISIONAL QUANTITY.	17	m²
#REF!	The Contractor is to supply and install INFINITY (product code: 34702) by Burmatex carpet tiles (https://www.burmatex.co.uk/contract-carpets/infinity-carpet-tiles/) to areas shown in Appendix B2. Carpet tiles will be from the manufacturer's standard colour range (colour: silver salt). PROVISIONAL QUANTITY.	17	m²
#REF!	Supply and fix new skirting boards to all walls to match existing Style: Pencil Round 18 x 169 mm. Locations as indicated in Appendix B2 Proposed Drawings. Painting of skirting boards allowed for in other item. PROVISIONAL QUANTITY.	18	m
#REF! 1.230b	SECTION 4: Mill Court - Unit X (Tenant: Star Crossed Beauty) Prime, prepare and decorate internal walls to ceiling height with one mist coat and two coats of Dulux Trade Diamond Matt Paint (Colour: Brilliant White) or equivalent breathable mineral- or water-based paint on agreement with the Contract Administrator. Preparation and application to follow manufacturers guidance and to BS 6150-6. Vinyl paints are not to be used. PROVISIONAL QUANTITY	73	m²
1.224b	Grind down floors to remove existing screed where this has failed in localised area PROVISIONAL QUANTITY	60	m²
#REF!	Flooring where existing screed removed to be treated with a self-levelling screed to achieve SR2 Level Rating. Joint into existing screed and floor finishes. Specification: Ardex K15 HB or equivalent installed to manufacturers instructions. PROVISIONAL QUANTITY.	60	m²
#REF!	The Contractor is to supply and install INFINITY (product code: 34702) by Burmatex carpet tiles (https://www.burmatex.co.uk/contract-carpets/infinity-carpet-tiles/) to areas shown in Appendix B2. Carpet tiles will be from the manufacturer's standard colour range (colour: silver salt). PROVISIONAL QUANTITY.	38	m²
#REF!	SECTION 4: Mill Court - Unit Y (Tenant: J Scientific Glass)		
1.238b	Prime, prepare and decorate internal walls to ceiling height with one mist coat and two coats of Dulux Trade Diamond Matt Paint (Colour: Brilliant White) or equivalent breathable mineral- or water-based paint on agreement with the Contract Administrator. Preparation and application to follow manufacturers guidance and to BS 6150-6. Vinyl paints are not to be used. PROVISIONAL QUANTITY	84	m²
	Grind down floors to remove existing screed where this has failed. Joint into existing screed and floor finishes.	60	m²



ITEM		QUANT	UNIT
#REF!	Flooring where existing screed removed to be treated with a self-levelling screed to achieve SR2 Level Rating. Specification: Ardex K15 HB or equivalent installed to manufacturers instructions. PROVISIONAL QUANTITY.	60	m²
#REF!	SECTION 4: Mill Court - Unit W (Tenant: TBC)		
1.244b	Prime, prepare and decorate internal walls to ceiling height with one mist coat and two coats of Dulux Trade Diamond Matt Paint (Colour: Brilliant White) or equivalent breathable mineral- or water-based paint on agreement with the Contract Administrator. Preparation and application to follow manufacturers guidance and to BS 6150-6. Vinyl paints are not to be used. PROVISIONAL QUANTITY	95	m²
1.245b	Grind down floors to remove existing screed where this has failed. Joint into existing screed and floor finishes. PROVISIONAL QUANTITY	60	m²
#REF!	Warehouse flooring where existing screed removed to be treated with a self-levelling screed to achieve SR2 Level Rating. Specification: Ardex A35 or equivalent installed to manufacturers instructions. PROVISIONAL QUANTITY.	60	m²
#REF!	ALL SECTIONS - Handover		
#REF!	Note: Each section must be protected from ongoing work in other sections by the Contractor upon completion. Any damage caused by movement of tools or materials through completed areas is to be rectified on completion of Section 4.	Note	
#REF!	Prior to handover the contractor is to undertake a deep clean of all internal surfaces including to floors, joinery, windows and all retained surfaces where works have been carried out. The contractor is to ensure that all areas are swept clean and debris removed. Price for each section below:	Price each section below	
#REF!	Section 1 ditto	1	Item
#REF!	Section 2 ditto	1	ltem
#REF!	Section 3 ditto	1	Item
#REF!	Section 4 ditto	1	Item
#REF!	The Contractor is to present to the Contract Administrator the cleaning goal recording document in accordance with PAS 64 on handover of each section. Price for each section below:	Price each section below	
#REF!	Section 1 ditto	1	Item
#REF!	Section 2 ditto	1	Item
#REF!	Section 3 ditto	1	Item
#REF!	Section 4 ditto	1	Item
#REF!	The Contractor is to present to the Contract Administrator the completion certificate in accordance with PAS 64 on handover of each section. Price for each section below:	Price each section below	
#REF!	Section 1 ditto	1	Item
#REF!	Section 2 ditto	1	Item
#REF!	Section 3 ditto	1	Item
#REF!	Section 4 ditto	1	Item
#REF!	Contractor on completion to provide O&M Manual with all test reports, certificates, guarantees etc. Price for each section below:	Price each section below	
#REF!	Section 1 ditto	1	Item
#REF!	Section 2 ditto	1	Item
#REF!	Section 3 ditto	1	Item
#REF!	Section 4 ditto	1	Item
#REF!	Contractor on completion to provide Waste Transfer Notes. Price for each section below:	Price each section below	
#REF!	Section 1 ditto	1	Item
#REF!	Section 2 ditto	1	Item
#REF!	Section 3 ditto	1	Item
#REF!	Section 4 ditto	1	Item
#REF!	Contractor on completion to provide the necessary information, test reports and certificates for the H&S File. Draft to be provided and updated on completion of each section. Price for each section below:	Price each section below	
#REF!	Section 1 ditto	1	Item
#REF!	Section 2 ditto	1	Item
#REF!	Section 3 ditto	1	Item
#REF!	Section 4 ditto	1	Item
	Total Carried To Main Summary		